



WN59JZR

report date: 2024-03-28

General information

Make	FIAT
Model	GRANDE PUNTO DYNAMIC
Colour	White
Year of manufacture	2009
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	41.5 mpg
Consumption extra urban	56.5 mpg
Consumption combined	49.6 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 2

Date	2021-07-31
Pictures	12
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-31
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2022-01-19
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	26
Total items failed	7

MOT #14	2021-01-09 10:42
MOT test number	384015663305
Result	✓ Passed
Next expiry date	2022-01-19
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Front and rear suspension components corroded

MOT #13	2020-01-20 11:43
MOT test number	849618454247
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

MOT #12	2020-01-20 11:43
MOT test number	268519237700
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Offside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #11** 2018-12-18 09:59**MOT test number** 643712249534**Result** ✓ Passed**Advice** Offside Rear Seat belt damaged but webbing not significantly weakened (5.2.2a)**Advice** Rear exhaust section corroding.**MOT #10** 2017-12-19 15:52**MOT test number** 627595581899**Result** ✓ Passed**Advice** Offside Rear Seat belt damaged but webbing not significantly weakened (5.2.2a)**MOT #9** 2016-12-15 14:55**MOT test number** 443961396090**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Seat belt cut but webbing not significantly weakened (5.2.2a)**Advice** Rear exhaust section corroding.**MOT #8** 2016-12-15 08:55**MOT test number** 355684662751**Result** ✗ Failed**Fail** Offside Rear Stop lamp not working (1.2.1b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear exhaust section corroding.**Advice** Nearside Front Seat belt cut but webbing not significantly weakened (5.2.2a)**Fail** Offside Front coil spring broken (2.4.C.1a)

**MOT #7** 2015-11-16 00:00**MOT test number** 584499369494**Result** ✓ Passed**MOT #6** 2014-11-12 11:25**MOT test number** 317906114363**Result** ✓ Passed**Advice** Nearside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**Notice** Rear exhaust deteriorating**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-09-06 11:45**MOT test number** 577219843246**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #4** 2013-09-02 11:05**MOT test number** 969075043292**Result** ✗ Failed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #3** 2013-08-29 15:16**MOT test number** 396791443237**Result** ✗ Failed**Notice** Small breather pipe cracking**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)

**MOT #2** 2013-08-16 15:56**MOT test number** 146998023264**Result** ✗ Failed**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**Notice** Both front tyres badly worn on the edges**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Notice** Small breather pipe cracking**MOT #1** 2012-09-19 12:21**MOT test number** 799993562236**Result** ✓ Passed**Advice** Nearside Front Upper Anti-roll bar ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)



Tax & MOT check

✕
Untaxed

Tax expired:
1 February 2022

✕
MOT

Expired:
19 January 2022

Tax status	Expired at 1 February 2022
Days left	818 days too late
MOT expiry date	19 January 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-09-25
Last registration	2021-01-09
Complete history	See info



Registration #1	2009-09-25	6 mi
Registration #2	2012-09-19	34.555 mi
Registration #3	2013-08-16	58.288 mi
Registration #4	2013-08-29	58.899 mi
Registration #5	2013-09-02	59.167 mi
Registration #6	2013-09-06	59.526 mi
Registration #7	2014-11-12	72.370 mi
Registration #8	2015-11-16	81.834 mi
Registration #9	2016-12-15	91.510 mi
Registration #10	2019-09-25	95.377 mi
Registration #11	2019-09-25	95.377 mi
Registration #12	2019-09-25	95.377 mi
Registration #13	2019-09-25	95.377 mi
Registration #14	2019-09-25	95.377 mi
Registration #15	2019-09-25	95.377 mi
Registration #16	2019-09-25	95.377 mi
Registration #17	2019-09-25	95.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1585 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	4924076