





report date: 2024-03-29

General information

Make	FORD
Model	B-MAX ZETEC
Colour	Red
Year of manufacture	2015
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	66 kW / 90 HP / 89 BHP
Max. torque	128 Nm at 4.000 rpm
Engine capacity	1.388 сс
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 2


Date 2021-06-05

Pictures 17

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date	2021-05-31
Pictures	10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT #5

YG64DPE

report date: 2024-03-29

2020-10-23 14:17

MOT history	
MOT expiry date	2025-03-03

MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	8

0 **Total items failed**

MOT #9	2024-03-04 08:13
MOT test number	647933212614
Result	✓ Passed
Next expiry date	2025-03-03

MOT #8	2023-10-11 10:52
MOT test number	435751112825
Result	✓ Passed

MOT #7	2022-10-21 09:29
MOT test number	673835216948
Result	./ Passed

MOT #6	2021-10-13 11:51
MOT test number	174248109006
Result	./ Passed

MOT test number	174248109006
Result	✓ Passed

MOT test number 698483410502 Result ✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice**

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #4 2020-10-23 13:22

MOT test number 959808134649

Result X Failed

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #3 2019-04-23 12:34

MOT test number 777935695196

Result

Passed

MOT #2 2018-04-26 10:45

MOT test number 796310796688

MOT #1 2017-12-06 11:05

MOT test number 992645912346

Result / Passed

Advice pressure

Offside Rear fluid misting around rear wheel cylinder connection. no sign of leak when under

Advice

Nearside Rear fluid misting around rear wheel cylinder connection. no sign of leak when under

pressure

CarCheck.co.uk page 4/11



YG64DPE report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	3 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this FORD? How many owners check it in the premium report and see all owner registrations. Download the full report	

Plate changes	More info >
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	UK NE
Plate since	
Current registration	NK NE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-02-24
Last registration	2024-03-04
Complete history	See info



Registration #1	2015-02-24	8 mi
Registration #2	2017-12-06	7.114 mi
Registration #3	2018-04-26	7.828 mi
Registration #4	2019-04-23	12.044 mi
Registration #5	2020-10-23	19.628 mi
Registration #6	2020-10-23	19.628 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	67%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2067 mm
Height	1604 mm
Length	4077 mm
Wheel base	2489 mm
Kerb weight	1760 kg
Max. allowed weight	1745 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 11/11