





report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV-4 D-4D XT-R
Colour	Black
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	340 Nm at 2.800 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	49.6 mpg
CO2 emission	150 g/km
CO2 label	F



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-08-20

Pictures 26

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



report date: 2024-03-29

B 4	\sim $-$			
10.71	α	- h	sto	rv
101	() I		510	II V
	•		-	. ,

(i))

MOT expiry date	2024-09-18
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	19
Total items failed	1

MOT #14	2023-09-19 09:56
MOT test number	760339101516
Result	✓ Passed
Next expiry date	2024-09-18

MOT #13	2022-07-26 15:08
MOT test number	956422198404
Result	✓ Passed

MOT #12	2021-07-30 12:12
MOT test number	678671612491
Result	✓ Passed

MOT #11	2021-01-12 15:54

MOT test number 846852235601

Result	✓ Passed
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

CarCheck.co.uk page 3/12



Result

YR10ZWM

report date: 2024-03-29

✓ Passed

MOT #10 2021-01-12 10:12 **MOT test number** 236179416353 Result × Failed **DANGEROUS** Offside Front Valve stem seriously damaged (5.2.3 (j)) **Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Nearside Rear Nail in tyre Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #9	2019-07-12 08:16
MOT test number	112317879029
Result	✓ Passed
MOT #8	2018-06-05 08:44
MOT test number	465973550882

MOT #7	2017-06-16 14:30
MOT test	number 803766297237
Result	✓ Passed
Advice	Offside Rear Valve stem slightly damaged (4.1.D.1e)
Advice (2.4.G.2)	Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
Advice	Offside Rear Shock absorber has a light misting of oil (2.7.3)
Advice (2.4.G.2)	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #6 2016-06-15 14:10

MOT test number 364593087155

Result ✓ Passed

MOT #5 2016-06-14 11:33

MOT test number 476623457974

Result X Failed

Fail Offside Front Upper Tie bar/rod ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt Drop link. (2.4.G.2)

MOT #4 2015-06-11 12:48

MOT test number 479422865142

Result
✓ Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Shock absorber has a light misting of oil (2.7.3)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #3 2014-06-13 13:07

MOT test number 697424664118

Result

Passed

MOT #2 2013-06-12 17:16

MOT test number 716563363103

Result \(\sqrt{Passed} \)

MOT #1 2013-02-15 15:28

MOT test number 558286843058

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check





Expires: 18 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	18 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



YR10ZWM report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner	history

*		
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full		DTA

	More info	>
Plate changes		
See in this check if this TOYOTA had different number plates.		
Number of plates		
Current registration	UK W	
Plate since		
Current registration	NK NA	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-06-29
Last registration	2023-09-19
Complete history	See info



Registration #1	2010-06-29	23 mi
Registration #2	2013-02-15	26.971 mi
Registration #3	2013-06-12	29.006 mi
Registration #4	2014-06-13	41.463 mi
Registration #5	2015-06-11	54.341 mi
Registration #6	2016-06-14	60.900 mi
Registration #7	2016-06-15	60.925 mi
Registration #8	2017-06-16	66.417 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		9.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
50482	
50501	
60566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1685 mm
Length	4365 mm
Wheel base	2560 mm
Kerb weight	1600 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	60 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

Engine number 2AD0317759