



report date: 2024-03-28

General information

| | |
|---------------------|------------------|
| Make | CITROEN |
| Model | C5 HDI EXCLUSIVE |
| Colour | Blue |
| Year of manufacture | 2010 |
| Top speed | 134 mph |
| 0 - 60 mph | 8.6 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 148 BHP |
| Max. torque | 340 Nm at 2.000 rpm |
| Engine capacity | 1.997 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 42.8 mpg |
| Consumption extra urban | 68.9 mpg |
| Consumption combined | 56.5 mpg |
| CO2 emission | 139 g/km |
| CO2 label | E |





MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-02-08 |
| MOT pass rate | 73 % |
| MOT passed | 11 |
| Failed MOT tests | 4 |
| Total advice items | 20 |
| Total items failed | 5 |

| | |
|------------------|--|
| MOT #15 | 2024-02-06 17:06 |
| MOT test number | 137710717480 |
| Result | ✓ Passed |
| Next expiry date | 2025-02-08 |
| Minor | Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |

| | |
|-----------------|--|
| MOT #14 | 2024-02-02 15:31 |
| MOT test number | 600881493966 |
| Result | ✗ Failed |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Fail | Nearside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i)) |
| Minor | Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) |
| Fail | Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii)) |

| | |
|-----------------|------------------|
| MOT #13 | 2023-01-23 15:45 |
| MOT test number | 517946963567 |
| Result | ✓ Passed |

**MOT #12** 2022-02-09 11:06**MOT test number** 487378703830**Result** ✓ Passed**MOT #11** 2021-02-03 10:31**MOT test number** 402306629480**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #10** 2021-01-27 15:24**MOT test number** 156102883114**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Fail** Nearside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2019-05-07 09:47**MOT test number** 770567889621**Result** ✓ Passed**Advice** Nearside Front brake pad warning wire broken**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #8** 2018-05-11 10:30**MOT test number** 214508099473**Result** ✓ Passed

**MOT #7** 2018-05-08 08:34**MOT test number** 807369348446**Result** ✗ Failed

Fail Offside Front Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #6 2017-05-16 13:17**MOT test number** 882560582259**Result** ✓ Passed

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)

Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)

Advice Under/trays fitted can not see components

MOT #5 2017-05-16 08:18**MOT test number** 222898805286**Result** ✗ Failed

Advice Under/trays fitted can not see components

Fail Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #4 2016-05-09 10:27**MOT test number** 900755632070**Result** ✓ Passed

Advice Nearside Rear Inner Brake pad(s) wearing thin (3.5.1g)



| | |
|---|------------------|
| MOT #3 | 2015-05-15 14:24 |
| MOT test number | 667295835168 |
| Result | ✓ Passed |
| <div>NoticeUnder-trays fitted obscuring some underside components</div> | |

| | |
|-----------------|------------------|
| MOT #2 | 2014-05-21 15:07 |
| MOT test number | 876351744115 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #1 | 2013-10-18 14:43 |
| MOT test number | 306541793460 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
8 February 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 February |
| Days left | 278 |
| MOT expiry date | 8 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 16 |
| First mileage registration | 2010-12-01 |
| Last registration | 2024-02-06 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2010-12-01 | 7 mi |
| Registration #2 | 2013-10-18 | 18.977 mi |
| Registration #3 | 2014-05-21 | 20.128 mi |
| Registration #4 | 2015-05-15 | 31.146 mi |
| Registration #5 | 2016-05-09 | 40.260 mi |
| Registration #6 | 2017-05-16 | 49.507 mi |
| Registration #7 | 2017-05-16 | 49.507 mi |
| Registration #8 | 2018-05-08 | 57.699 mi |
| Registration #9 | 2019-05-09 | 65.891 mi |
| Registration #10 | 2020-05-10 | 74.083 mi |
| Registration #11 | 2021-05-11 | 82.275 mi |
| Registration #12 | 2022-05-12 | 90.467 mi |
| Registration #13 | 2023-05-13 | 98.659 mi |
| Registration #14 | 2024-02-06 | 106.851 mi |
| Registration #15 | 2024-02-06 | 106.851 mi |
| Registration #16 | 2024-02-06 | 106.851 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 87% |
| Children | 78% |
| Pedestrian | 46% |
| Safety systems | 89% |
| Overall rating | 77% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1789 mm |
| Height | 1491 mm |
| Length | 4329 mm |
| Wheel base | 2608 mm |
| Kerb weight | 1320 kg |
| Max. allowed weight | 1885 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | DYXR4001295 |