





# General information

Make	CITROEN
Model XSARA HDI DESIRE PICASSO E4	
Colour	Silver
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	13.8 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	89 BHP
Max. torque	215 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg





## Internet history

Entry 1

Date

2021-07-31

4

Pictures

Listing price

View report



source: autotrader.co.uk



# MOT history

MOT #15 2021-07-13 14:59
<b>MOT test number</b> 780501790630
Result X Failed
Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge edge worn and perished in treads and on outer sidewall. (5.2.3 (e))
<b>Fail</b> Offside Front Outer Seat belt anchorage prescribed area strength or continuity significantly reduced sill corroded and holed within prescribed area of drivers seat mounting. (7.1.1 (a) (i))
Fail Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice Timing belt has slight noise when engine is running, advise history look up for when was replaced.
Fail Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Advice Nearside Rear Outer Child Seat fitted not allowing full inspection of adult belt
<b>Pass with rectification</b> Offside Front Headlamp aim too low (4.1.2 (a))
<b>Advice</b> Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn both starting to perish and both have slight movement. (5.1.2 (b) (i))
Advice Nearside Front Outer sill panel corroded and holed but outside any prescribed areas.
Fail   Offside Rear Position lamp not working (4.2.1 (a) (ii))
Advice Offside Rear Outer Child Seat fitted not allowing full inspection of adult belt
<b>Fail</b> Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #14		2019-11-14 14:39
MOT test	number	893174569729
Result		✓ Passed
Advice	Both front outer sill panels starting to corrode - keep in check	
Advice	Central Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Items removed from driver's view prior to test	



G	F	5	6	V	V	K	G
	rep	ort	da	te:	20	24-0	3-29

MOT #13	2019-11-14 10:32
MOT test number	545792489393
Result	🗙 Failed
Advice Items removed from driver's view prior to test	
<b>Fail</b> Offside Rear Inner Tyre has a cut in excess of the requirements deep enough to side wall (5.2.3 (d) (i))	o reach the ply or cords
Advice Nearside Rear Nail in tyre	
Advice Both front outer sill panels starting to corrode - keep in check	
Advice Central Rear Child Seat fitted not allowing full inspection of adult belt	
Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords	s (5.2.3 (d) (i))

MOT #12	2018-11-28 09:55
MOT test number	870747990193
Result	✓ Passed

MOT #11	2018-11-28 09:55
MOT test number	222827808436
Result	× Failed
Pass with rectification	Offside Registration plate lamp inoperative in the case of a single lamp or all

lamps (4.7.1 (b) (ii))

MOT #10		2017-11-29 10:39
MOT test	number	580382559876
Result		✓ Passed
Advice	Both rear tyres inner sidewalls starting to split, no visible cords, keep in check	
Advice	Rear Child Seat fitted not allowing full inspection of adult belt centre	



G	F56WKG
	report date: 2024-03-29

MOT #9	2016-11-24 16:26
MOT test number	950878405822
Result	✓ Passed
Advice O/s/f seat belt frayed	
Advice N/s/f tyre heavily worn edges	
Advice Front pads worn low	
Advice O/s/f tyre perished and cracked wall and tread	
Advice Rear tyres cracked and split inner tyre walls	
Advice Front discs lipped and worn	
MOT #8	2016-11-24 16:26

2016-11-24 16:26
291869853362
🗙 Failed

MOT #7	2015-11-03 10:50
MOT test number	695216913152
Result	✓ Passed
Advice Offside Front Seat belt stitching slightly frayed (5.2.2b)	





MOT #6		2014-11-07 09:24
MOT test	number	376681214349
Result		Passed
Notice	Passenger seat(s) missing at time of test	
MOT #5		2013-11-26 11:04
MOT test	number	626310133395
Result		✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Under-trays fitted obscuring some underside components	
Notice	Passenger seat(s) missing at time of test	

MOT #4	2012-11-09 09:18
MOT test number	146254912307
Result	✓ Passed
Notice Passenger seat(s) missing at time of test   Advice Offside Front Seat belt stitching slightly fraved (5.2.2b)	
Advice Offside Front Seat belt stitching slightly frayed (5.2.2b)	

MOT #3	2011-11-17 10:27
MOT test number	229961021383
Result	✓ Passed
<b>Notice</b> Driver seat belt slightly frayed	

MOT #2	2010-11-10 08:39
MOT test number	901454610310
Result	✓ Passed





MOT #1	2009-11-23 10:38
MOT test number	550167829346
Result	✓ Passed





## Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date		
Category		Lawer
Туре	(*******	
Damage 2		AMPLE
Damage 2		E CONTRACTOR
Date		
Category		AMP
Туре		

#### Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





## Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





## Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

******	
**********	
*******	
******	
**********	
*******	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	
Plate since	
Current registration	
Plate since	





## Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2006-11-27
Last registration	2021-07-13
Complete history	See info



Registration #1	2006-11-27	14 mi
Registration #2	2009-11-23	12.422 mi
Registration #3	2010-11-10	16.459 mi
Registration #4	2011-11-17	19.595 mi
Registration #5	2012-11-09	26.036 mi
Registration #6	2013-11-26	48.684 mi
Registration #7	2014-11-07	67.619 mi
Registration #8	2015-11-03	81.994 mi
Registration #9	2016-11-24	86.236 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		11.777 mi



Safety ratings		
NCAP rating		
Video	see crash video	
Dimensions & weight		
Width		1751 mm
Height		1637 mm
Length		4276 mm
Wheel base		2760 mm
Kerb weight		1300 kg
Max. allowed weight		1850 kg
Additional information		
Fuel tank capacity		60 I
Fuel delivery		Direct Injection
Number of doors		5
Number of seats		5
Number of axles		2
Engine number		JB663111139