



General information

Make	MINI
Model	CLUBMAN JOHN COOPER WORKS
Colour	Grey
Year of manufacture	2016
Top speed	153 mph
0 - 60 mph	6.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	228 BHP
Max. torque	320 Nm at 1.250 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.0 mpg
Consumption extra urban	54.3 mpg
Consumption combined	42.2 mpg
CO2 emission	147 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-02
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-03-14
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	16
Total items failed	2

MOT #6	2024-03-15 15:48
MOT test number	978685648355
Result	✓ Passed
Next expiry date	2025-03-14
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5	2023-03-08 12:21
MOT test number	852151298902
Result	✓ Passed
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #4**

2023-03-07 15:56

MOT test number

746508771775

Result**✗ Failed****Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Nearside Rear Outer Tyre has a tear, caused by separation or partial failure of its structure side wall marked yellow (5.2.3 (d) (ii))**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Rear Outer Tyre has a tear, caused by separation or partial failure of its structure side wall marked yellow (5.2.3 (d) (ii))**MOT #3**

2022-03-03 09:41

MOT test number

364900633651

Result**✓ Passed****Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm 225/40R18 92Y RUNFLAT (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3-4mm (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 3-4mm (5.2.3 (e))**MOT #2**

2021-01-08 09:34

MOT test number

382445579221

Result**✓ Passed****Advice** Undertrays fitted obscuring inspection of some components**MOT #1**

2019-11-01 10:47

MOT test number

237059491279

Result**✓ Passed**



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
14 March 2025

Tax status	Valid until 1 January
Days left	248
MOT expiry date	14 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-11-15
Last registration	2024-03-15
Complete history	See info



Registration #1	2016-11-15	16 mi
Registration #2	2019-11-01	34.057 mi
Registration #3	2021-01-08	45.932 mi
Registration #4	2022-03-22	55.277 mi
Registration #5	2023-03-22	65.277 mi
Registration #6	2023-03-22	75.277 mi
Registration #7	2023-03-22	85.277 mi
Registration #8	2024-03-15	95.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	79%
Children	73%
Pedestrian	66%
Safety systems	56%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1727 mm
Height	1414 mm
Length	3874 mm
Wheel base	1932 mm
Kerb weight	1280 kg
Max. allowed weight	1685 kg

Additional information

Fuel tank capacity	44 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	F392H243