





# General information

| Make                | FIAT               |
|---------------------|--------------------|
| Model               | DOBLO 16V MULTIJET |
| Colour              | White              |
| Year of manufacture | 2014               |
| Top speed           | 102 mph            |
| Gearbox             | 5 speed Manual     |

# Engine & fuel consumption

| Power                   | 105 BHP             |
|-------------------------|---------------------|
| Max. torque             | 290 Nm at 1.500 rpm |
| Engine capacity         | 1.598 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 42.2 mpg            |
| Consumption extra urban | 60.1 mpg            |
| Consumption combined    | 52.3 mpg            |
| CO2 emission            | 144 g/km            |
| CO2 label               | F                   |





# Internet history Entry 1 Date 2021-09-15 Pictures 8 Listing price View report



AutoTrader Highly Rated FOR OUR CUSTOMER SERVICE 2021





source: cargurus.co.uk



# MOT history

| MOT expiry date    | 2024-09-10 |
|--------------------|------------|
| MOT pass rate      | 80 %       |
| MOT passed         | 8          |
| Failed MOT tests   | 2          |
| Total advice items | 8          |
| Total items failed | 8          |

| MOT #10   |  | 2023-09-11 08:22 |
|---|--|------------------|
| MOT test  | number   | 294366711269     |
| Result  |  | ✓ Passed         |
| <b>Next expiry date</b> 2024-09-10  |  |                  |
| Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i)) |  |                  |
| Minor   | Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i)) |                  |

| MOT #9   |   | 2023-09-04 13:52 |
|--|---|------------------|
| MOT test number  |   | 519910601835     |
| Result   |   | × Failed         |
| Pass with rectification  | Offside Position lamp not working (4.2.1 (a) (ii))                    |                  |
| Advice Offside Front Ty  | re worn close to legal limit/worn on edge (5.2.3 (e))                 |                  |
| Pass with rectification  | Offside Side repeater not working (4.4.1 (a) (ii))                    |                  |
| Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i)) |   |                  |
| Fail         Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))                            |   |                  |
| Advice Nearside Front  | Tyre worn close to legal limit/worn on edge (5.2.3 (e))               |                  |
| Pass with rectification  | Nearside Stop lamp(s) not working (4.3.1 (a) (ii))                    |                  |
| Minor Offside Front Ant  | i-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 | (b) (i))         |





| MOT #8  | 2022-08-18 15:57 |
|---|------------------|
| MOT test number   | 529762492796     |
| Result  | ✓ Passed         |
|   |                  |
| MOT #7  | 2021-09-10 14:22 |
| MOT test number   | 567183953083     |
| Result  | ✓ Passed         |
|   |                  |
| MOT #6  | 2021-09-09 15:03 |
| MOT test number   | 771644188468     |
| Result  | 🗙 Failed         |
| Fail         Offside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3)                    | .4 (a) (i))      |
| <b>Fail</b> Front Brake disc significantly and obviously worn (1.1.14 (a) (i))                                  |                  |
| Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))                                |                  |
| Fail         Offside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i)) |                  |
| Fail         Front Position lamp not working both (4.2.1 (a) (ii))  |                  |

| MOT #5          | 2020-11-11 15:17 |
|-----------------|------------------|
| MOT test number | 568424257119     |
| Result          | ✓ Passed         |

| МОТ #4  | 2019-11-18 12:38 |
|---|------------------|
| MOT test number   | 507112736154     |
| Result  | ✓ Passed         |
| Advice Nearside Front Wheel bearing has slight play very slight (5.1.3 (a) (i)) |                  |

| MOT #3          | 2018-11-19 16:07 |
|-----------------|------------------|
| MOT test number | 496096324067     |
| Result          | ✓ Passed         |





| MOT #2          | 2017-12-11 11:49 |
|-----------------|------------------|
| MOT test number | 908560914707     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #1          | 2017-01-31 07:50 |
| MOT test number | 545188740271     |
| Result          | ✓ Passed         |



Tax & MOT check

| ✓<br>Taxed<br>Tax due:<br>1 October 2024 | ✓<br>MOT<br>Expires:<br>10 September 2024 |
|--|---|
| Tax status                               | Valid until 1 October                     |
| Days left                                | 156                                       |
| MOT expiry date                          | 10 September 2024                         |
| Full MOT history                         | See MOT history                           |

# Tax calculation

| Vehicle class             | 39         |
|---------------------------|------------|
| Standard rate (12 months) | £ 275,00,- |
| Standard rate (6 months)  | £ 151,25,- |





### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1  |         |
|-----------|---------|
| Date      |         |
| Category  | Lamp    |
| Туре      |         |
| Damage 2  | AMPLE   |
| Duniuge 2 | E E E E |
| Date      | J.      |
| Category  | amer    |
| Туре      |         |

### Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4 10.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 10.200 |





## Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| and the second |             |
|---|-------------|
| **********  |             |
| *******   |             |
| ******  |             |
| **********  |             |
| *******   |             |
|   | More info > |
| Plate changes   |             |
| See in this check if this FIAT had different number plates.   |             |
| Number of plates  | ,           |
| Current registration  |             |
| Plate since   |             |
| Current registration  |             |
| Plate since   |             |
|   | More info > |





### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.


| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |





# Mileage check

| Odometer                   | In miles        |
|----------------------------|-----------------|
| Mileage registrations      | 12              |
| First mileage registration | 2014-02-04      |
| Last registration          | 2023-09-11      |
| Complete history           | <u>See info</u> |



| Registration #1  | 2014-02-04 | 19 mi      |
|------------------|------------|------------|
| Registration #2  | 2017-01-31 | 6.785 mi   |
| Registration #3  | 2017-12-11 | 7.010 mi   |
| Registration #4  | 2018-11-19 | 13.697 mi  |
| Registration #5  | 2019-11-18 | 22.987 mi  |
| Registration #6  | 2020-11-11 | 32.774 mi  |
| Registration #7  |            | 11.777 mi  |
| Registration #8  |            | 11.777 esi |
| Registration #9  |            | 11.777 mi  |
| Registration #10 |            | 11.777 esi |
| Registration #11 |            | 11.777 mi  |
|                  |            |            |





# Car features

| S0225  | Air conditioning |
|--------|------------------|
| \$0295 |                  |
| 50482  |                  |
| \$0501 |                  |
| S0566  |                  |
| S0567  |                  |
| S0569  |                  |

# Safety ratings

**NCAP** rating

Video

see crash video



| Dimensions & weight             |                    |
|---------------------------------|--------------------|
| Width                           | 1789 mm            |
| Height                          | 1845 mm            |
| Length                          | 4390 mm            |
| Kerb weight                     | 1445 kg            |
| Max. allowed weight             | 2430 kg            |
| Additional information          |                    |
| Fuel tank capacity              | 60 I               |
| Fuel delivery                   | Direct Injection   |
| Number of doors                 | 4                  |
| Number of seats                 | 2                  |
| Engine number<br>CarCheck.co.uk | 7097830 page 12/12 |