




report date: 2024-03-28

General information

Make	FIAT
Model	500 C LOUNGE
Colour	Black
Year of manufacture	2011
Top speed	107 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	145 Nm at 1.900 rpm
Engine capacity	875 cc
Cylinders	2
Fuel type	Petrol
Consumption city	57.7 mpg
Consumption extra urban	76.4 mpg
Consumption combined	68.9 mpg
CO2 emission	95 g/km
CO2 label	A






Internet history

Entry 1

Date	2021-11-07
Pictures	27
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-27
MOT pass rate	52 %
MOT passed	11
Failed MOT tests	10
Total advice items	47
Total items failed	27

MOT #21	2023-10-24 14:29
MOT test number	364458687878
Result	✓ Passed
Next expiry date	2024-10-27
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #20	2023-10-16 15:00
MOT test number	768614600880
Result	✗ Failed
Fail	Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
Fail	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Service brake grabbing severely (1.2.1 (c))
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Headlamp not working on main beam (4.1.1 (a) (ii))
Fail	Front Exhaust has a major leak of exhaust gases (6.1.2 (a))
Fail	Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #19**

2023-10-12 16:21

MOT test number

474485108164

Result**✗ Failed**

- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Central Rear Exhaust has a minor leak of exhaust gases Exhaust has been repaired using tape and wire (6.1.2 (a))
- Fail** Rear Registration plate does not conform to the specified requirements (0.1 (d))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Headlamp not working on main beam (4.1.1 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged Outer wall (5.2.3 (d) (ii))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Front Registration plate does not conform to the specified requirements (0.1 (d))
- Fail** Nearside Front Service brake lagging in operation (1.2.1 (d))
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Offside Headlamp not working on main beam (4.1.1 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #18** 2022-10-26 08:31**MOT test number** 310541998606**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**MOT #17** 2021-10-28 13:40**MOT test number** 555239855382**Result** ✓ Passed**MOT #16** 2021-10-28 13:40**MOT test number** 145783851022**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #15** 2021-05-26 14:31**MOT test number** 925712480143**Result** ✓ Passed**Advice** Nearside Front Oil leak, but not excessive slight leak from gearbox area (8.4.1 (a) (i))**MOT #14** 2021-05-26 10:50**MOT test number** 899991149979**Result** ✗ Failed**Fail** Nearside Front Macpherson strut pin or bush excessively worn excessive play in top mount (5.3.4 (a) (i))**Fail** Nearside Front Headlamp not working on main beam also includes DRL (4.1.1 (a) (ii))**Advice** Nearside Front Oil leak, but not excessive slight leak from gearbox area (8.4.1 (a) (i))

**MOT #13**

2020-06-17 16:10

MOT test number

320784993315

Result

✓ Passed

Advice Exhaust hangers corroded**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #12**

2020-06-17 09:27

MOT test number

443527465750

Result

✗ Failed

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Exhaust hangers corroded**Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #11**

2019-05-02 15:52

MOT test number

726735151072

Result

✓ Passed

Advice Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

**MOT #10** 2019-04-29 14:00**MOT test number** 745628561602**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Upper Shock absorbers has a slightly worn bush (5.3.2 (c))**MOT #9** 2018-04-06 11:04**MOT test number** 228590011587**Result** ✓ Passed**Advice** Offside Front tyre starting to perish.**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front tyre starting to perish.**Advice** Offside Rear coil spring corroded (2.4.C.1b)**MOT #8** 2018-04-06 09:04**MOT test number** 673119137497**Result** ✗ Failed**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Starting to perish.**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front starting to perish.**Fail** Offside Rear Upper Shock absorber has an excessively worn bush (2.7.4)

**MOT #7** 2017-04-01 07:59**MOT test number** 501145382962**Result** ✓ Passed**Advice** Nearside Rear Outer Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Shock absorber has a slightly worn bush (2.7.4)**MOT #6** 2016-04-06 15:25**MOT test number** 899603653289**Result** ✓ Passed**MOT #5** 2016-04-06 14:20**MOT test number** 759213871458**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #4** 2015-04-14 10:55**MOT test number** 399284705155**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

**MOT #3** 2015-04-13 09:01**MOT test number** 315223205153**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Boot release faulty**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Registration plate lamp not working (1.1.C.1d)**MOT #2** 2015-03-24 14:22**MOT test number** 135613785023**Result** ✗ Failed**Fail** Registration plate lamp not working (1.1.C.1d)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Notice** Boot release faulty**MOT #1** 2014-03-31 11:52**MOT test number** 548830894065**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
27 October 2024

Tax status	Valid until 1 January
Days left	246
MOT expiry date	27 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	RV11UTH
Plate since	2024-03-28
Current registration	RV11UTH
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2011-03-31
Last registration	2023-10-24
Complete history	See info



Registration #1	2011-03-31	12 mi
Registration #2	2014-03-31	24.294 mi
Registration #3	2015-03-24	31.371 mi
Registration #4	2015-04-13	31.495 mi
Registration #5	2015-04-14	31.495 mi
Registration #6	2016-04-06	40.841 mi
Registration #7	2016-04-06	40.841 mi
Registration #8	2017-04-01	52.922 mi
Registration #9	2018-04-06	62.919 mi
Registration #10	2018-04-06	62.919 mi
Registration #11	2019-04-29	70.780 mi
Registration #12	2019-05-02	70.780 mi
Registration #13	2019-05-02	70.780 mi
Registration #14	2019-05-02	70.780 mi
Registration #15	2019-05-02	70.780 mi
Registration #16	2019-05-02	70.780 mi
Registration #17	2019-05-02	70.780 mi
Registration #18	2019-05-02	70.780 mi
Registration #19	2019-05-02	70.780 mi
Registration #20	2019-05-02	70.780 mi
Registration #21	2019-05-02	70.780 mi
Registration #22	2019-05-02	70.780 mi
Registration #23	2019-05-02	70.780 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	930 kg
Max. allowed weight	1370 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	0022171