



report date: 2024-03-29

General information

Make	NISSAN
Model	PIXO N-TEC
Colour	Grey
Year of manufacture	2010
Top speed	96 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-08-01
Pictures	14
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-05
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	30
Total items failed	8

MOT #15	2023-08-04 15:10
---------	------------------

MOT test number	793728791854
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-08-05
------------------	------------

Advice	Nearside Rear shock absorber dust cover corroded
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #14**

2023-07-21 08:00

MOT test number

893361529097

Result

✗ Failed

- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Rear Suspension arm corroded and seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear shock absorber dust cover corroded
- Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #13

2022-08-06 10:06

MOT test number

496009688833

Result

✓ Passed

- Advice** Nearside Rear shock absorber dust cover corroded
- Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Offside Rear spring cup corroded but not seriously weakened
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #12**

2022-07-22 08:47

MOT test number

403787449512

Result

✗ Failed

- Advice** Nearside Rear shock absorber dust cover corroded
- Fail** Nearside Rear Suspension arm corroded and seriously weakened (5.3.3 (b) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Offside Rear spring cup corroded but not excessively
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))

MOT #11

2021-07-31 10:38

MOT test number

784165798225

Result

✓ Passed

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #10

2021-07-30 10:18

MOT test number

983581409616

Result

✗ Failed

- Fail** Horn not working (7.7 (a) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #9

2020-11-23 13:58

MOT test number

448004992396

Result

✓ Passed

- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #8** 2020-11-17 12:14**MOT test number** 498275997130**Result** ✗ Failed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))**MOT #7** 2019-11-26 13:15**MOT test number** 276711806084**Result** ✓ Passed**MOT #6** 2018-11-29 12:45**MOT test number** 909791439847**Result** ✓ Passed**MOT #5** 2017-11-22 11:08**MOT test number** 400158579395**Result** ✓ Passed**MOT #4** 2016-11-28 10:44**MOT test number** 779560819871**Result** ✓ Passed**MOT #3** 2015-11-13 14:07**MOT test number** 330319006579**Result** ✓ Passed



MOT #2	2014-11-26 11:11
MOT test number	539090334363
Result	✓ Passed

MOT #1	2013-11-29 13:15
MOT test number	358043333332
Result	✓ Passed

Notice N/s rear tyre on 1.6mm at time off test



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
5 August 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	5 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-12-02
Last registration	2023-08-04
Complete history	See info



Registration #1	2010-12-02	29 mi
Registration #2	2013-11-29	26.762 mi
Registration #3	2014-11-26	34.742 mi
Registration #4	2015-11-13	42.744 mi
Registration #5	2016-11-28	51.124 mi
Registration #6	2017-11-22	58.866 mi
Registration #7	2018-11-29	67.026 mi
Registration #8	2019-11-26	75.374 mi
Registration #9	2020-11-17	82.470 mi
Registration #10	2020-11-17	82.470 mi
Registration #11	2020-11-17	82.470 mi
Registration #12	2020-11-17	82.470 mi
Registration #13	2020-11-17	82.470 mi
Registration #14	2020-11-17	82.470 mi
Registration #15	2020-11-17	82.470 mi
Registration #16	2020-11-17	82.470 mi
Registration #17	2020-11-17	82.470 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	112085