



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 SPORT
Colour	Grey
Year of manufacture	2008
Top speed	115 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-02-05
Pictures	12
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-01-28
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	17
Total items failed	6

MOT #16 2024-01-25 12:07

MOT test number 880019422206

Result ✓ Passed

Next expiry date 2025-01-28

- Advice** Items removed from driver's view prior to test
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Guards fitted to rear of car
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #15 2023-01-16 17:31

MOT test number 378134926041

Result ✓ Passed

MOT #14 2022-01-12 16:10

MOT test number 987442616658

Result ✓ Passed

**MOT #13** 2021-01-29 14:51**MOT test number** 259551817533**Result** ✓ Passed

Advice Inner Brake disc worn, pitted or scored, but not seriously weakened all discs front and rear (1.1.14 (a) (ii))

MOT #12 2021-01-20 11:00**MOT test number** 468460337700**Result** ✗ Failed

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Inner Brake disc worn, pitted or scored, but not seriously weakened all discs front and rear (1.1.14 (a) (ii))

Fail Brake fluid significantly below minimum mark (1.1.10 (d) (ii))

MOT #11 2019-05-09 15:51**MOT test number** 250472131218**Result** ✓ Passed**MOT #10** 2018-03-02 15:53**MOT test number** 724639015302**Result** ✓ Passed**MOT #9** 2017-10-30 16:53**MOT test number** 593208391385**Result** ✓ Passed**MOT #8** 2016-10-31 15:12**MOT test number** 248567687315**Result** ✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2015-11-12 15:00**MOT test number** 988308891099**Result** ✓ Passed**Advice** Tyre worn close to the legal limit both front (4.1.E.1)**MOT #6** 2015-11-09 11:04**MOT test number** 841859860751**Result** ✗ Failed**Advice** Tyre worn close to the legal limit both front (4.1.E.1)**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #5** 2014-11-10 11:29**MOT test number** 735254214395**Result** ✓ Passed**MOT #4** 2013-11-11 11:43**MOT test number** 507395013373**Result** ✓ Passed**MOT #3** 2012-10-15 13:00**MOT test number** 456699082223**Result** ✓ Passed**Notice** Cut to nearside front tyre but not to cords.**Notice** Cut to offside front tyre but not to cords.

**MOT #2** 2011-11-08 09:44**MOT test number** 316352311333**Result** ✓ Passed**Notice** Nail in offside rear tyre (two nails)**Notice** Nail in nearside front tyre (two nail)**MOT #1** 2011-11-07 11:39**MOT test number** 916461511338**Result** ✗ Failed**Notice** Offside mirror cover and side repeater lenses is missing and not affecting indicator**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Headlamp aim too low (1.8)**Notice** Nail in offside rear tyre (two nails)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Nail in nearside front tyre (two nail)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
28 January 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	28 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	LR58ZGW
Plate since	2024-03-29
Current registration	LR58ZGW
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-11-14
Last registration	2024-01-25
Complete history	See info



Registration #1	2008-11-14	11 mi
Registration #2	2011-11-07	7.975 mi
Registration #3	2011-11-08	7.984 mi
Registration #4	2012-10-15	10.703 mi
Registration #5	2013-11-11	20.866 mi
Registration #6	2014-11-10	35.258 mi
Registration #7	2015-11-09	49.143 mi
Registration #8	2015-11-12	49.464 mi
Registration #9	2016-10-31	61.942 mi
Registration #10	2016-10-31	61.942 mi
Registration #11	2016-10-31	61.942 mi
Registration #12	2016-10-31	61.942 mi
Registration #13	2016-10-31	61.942 mi
Registration #14	2016-10-31	61.942 mi
Registration #15	2016-10-31	61.942 mi
Registration #16	2016-10-31	61.942 mi
Registration #17	2016-10-31	61.942 mi
Registration #18	2016-10-31	61.942 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1289 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	153102