



CITROËN




report date: 2024-03-29

## General information

Make	CITROEN
Model	C5 EXCLUSIVE HDI
Colour	Silver
Year of manufacture	2008
Top speed	139 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	210 BHP
Max. torque	440 Nm at 1.900 rpm
Engine capacity	2.720 cc
Cylinders	6
Fuel type	Diesel
Consumption city	23.7 mpg
Consumption extra urban	43.5 mpg
Consumption combined	33.2 mpg
CO2 emission	223 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-07-16
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk

**MOT history**

<b>MOT expiry date</b>	2023-12-14
<b>MOT pass rate</b>	71 %
<b>MOT passed</b>	12
<b>Failed MOT tests</b>	5
<b>Total advice items</b>	28
<b>Total items failed</b>	15

**MOT #17** 2023-12-06 12:22**MOT test number** 977358095441**Result** ✗ Failed

**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Nearside Seat belt anchorage prescribed area is corroded but not considered excessive inner sill area (7.1.1 (a) (i))

**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**Advice** Nearside Rear brake calliper damp

**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Central Rear Seat belt buckle slightly damaged clasp cover missing (7.1.2 (d))

**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Fail** Nearside Front Suspension unit leaking (5.3.5 (c))

**Fail** Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**Advice** Offside Seat belt anchorage prescribed area is corroded but not considered excessive inner sill area (7.1.1 (a) (i))

**Fail** Windscreen washer not working (3.5 (a))

**Advice** Brake master cylinder close to minimum mark (1.1.10 (d) (i))

**Fail** Offside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))

**MOT #16**

2022-12-15 08:47

**MOT test number**

448645736089

**Result**

✓ Passed

- Advice** Nearside Front brake pad sensor wires broken
- Advice** Nearside Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Central Rear seat belt clasp cover missing
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front brake pad sensor wires broken

**MOT #15**

2022-12-07 10:07

**MOT test number**

949546629419

**Result**

✗ Failed

- Advice** Offside Front brake pad sensor wires broken
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Nearside Front Suspension unit leaking (5.3.5 (c))
- Advice** Nearside Front brake pad sensor wires broken
- Advice** Nearside Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Fail** Offside Front Suspension unit leaking (5.3.5 (c))
- Advice** Central Rear seat belt clasp cover missing

**MOT #14**

2021-12-11 14:08

**MOT test number**

160378004197

**Result**

✓ Passed

- Advice** Shock absorbers has light misting of oil both front (5.3.2 (b))

**MOT #13**

2021-11-28 17:04

**MOT test number**

952982346675

**Result**

✗ Failed

**Advice**

Front Shock absorbers has light misting of oil both sides (5.3.2 (b))

**Fail**

Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Fail**

Offside Front Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Fail**

Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**Fail**

Nearside Front Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Fail**

Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**Fail**

Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #12**

2020-07-23 12:48

**MOT test number**

389059356033

**Result**

✓ Passed

**Advice**

Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**Advice**

Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #11**

2019-07-16 08:10

**MOT test number**

390642721473

**Result**

✓ Passed

**Advice**

Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #10**

2018-07-28 10:05

**MOT test number**

225329958739

**Result**

✓ Passed

**Advice**

Tyre slightly damaged/cracking or perishing both front (5.2.3 (d) (i))

**MOT #9** 2017-08-05 12:15**MOT test number** 617920798151**Result** ✓ Passed**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**Advice** Undertrays fitted**Advice** Offside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt insecure (2.5.C.1a)**Advice** Nearside Rear Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**MOT #8** 2016-08-02 15:47**MOT test number** 535079702978**Result** ✓ Passed**MOT #7** 2016-08-02 08:52**MOT test number** 229442736106**Result** ✗ Failed**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**MOT #6** 2015-07-27 11:32**MOT test number** 458018705297**Result** ✓ Passed**MOT #5** 2014-07-21 14:03**MOT test number** 797502804259**Result** ✓ Passed**MOT #4** 2013-08-05 10:40**MOT test number** 898367813261**Result** ✓ Passed



MOT #3	2012-09-05 11:50
MOT test number	116829242225
Result	✓ Passed
MOT #2	2011-09-06 13:52
MOT test number	569429041273
Result	✓ Passed
MOT #1	2011-09-05 16:48
MOT test number	768458141200
Result	✗ Failed
Fail	Windscreen washer provides insufficient washer liquid (8.2.3)



Tax & MOT check

✕  
Untaxed

Tax expired:  
9 December 2023

✕  
MOT

Expired:  
14 December 2023

Tax status	Expired at 9 December 2023
Days left	142 days too late
MOT expiry date	14 December 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-09-01
Last registration	2023-12-06
Complete history	<a href="#">See info</a>



Registration #1	2008-09-01	24 mi
Registration #2	2011-09-05	28.344 mi
Registration #3	2011-09-06	28.344 mi
Registration #4	2012-09-05	34.328 mi
Registration #5	2013-08-05	38.485 mi
Registration #6	2014-07-21	41.039 mi
Registration #7	2015-07-27	46.851 mi
Registration #8	2016-08-02	49.422 mi
Registration #9	2016-08-02	49.422 mi
Registration #10	2017-08-05	55.541 mi
Registration #11	2018-08-05	55.541 mi
Registration #12	2019-08-05	55.541 mi
Registration #13	2020-08-05	55.541 mi
Registration #14	2021-08-05	55.541 mi
Registration #15	2022-08-05	55.541 mi
Registration #16	2023-08-05	55.541 mi
Registration #17	2024-08-05	55.541 mi
Registration #18	2025-08-05	55.541 mi
Registration #19	2026-08-05	55.541 mi

More info >



Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)

Dimensions & weight

Width	1853 mm
Height	1456 mm
Length	4779 mm
Wheel base	2815 mm
Kerb weight	1766 kg
Max. allowed weight	2310 kg

Additional information

Fuel tank capacity	71 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	TRD20311467