




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	SCIROCCO R DSG
Colour	Black
Year of manufacture	2010
Top speed	155 mph
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	265 BHP
Max. torque	350 Nm at 2.500 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.3 mpg
CO2 emission	187 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-09-03
Pictures	7
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-09
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	25
Total items failed	6

MOT #14	2023-10-10 12:20
MOT test number	195080034181
Result	✓ Passed
Next expiry date	2024-10-09
Advice	Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #13	2023-10-10 12:20
MOT test number	884532664189
Result	✗ Failed
Pass with rectification	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Nearside Headlamp not working on main beam (4.1.1 (a) (ii))
Advice	Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))



MOT #12	2022-09-15 14:34
MOT test number	875500537798
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2021-09-14 14:56
MOT test number	222203865358
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #10**

2021-09-03 13:24

MOT test number

542710103102

Result

✗ Failed

DANGEROUS Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps Both (4.7.1 (b) (ii))**MAJOR** Headlamp levelling device inoperative (4.1.5 (a))**MAJOR** Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Exhaust noisy (8.1.1 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Headlamp cleaning device for LED or HID headlamp inoperative (4.1.6 (a) (ii))**Advice** Suspension modified**MAJOR** Nearside Rear Wheel bearing has excessive play (5.1.3 (a) (i))**MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))**MOT #9**

2020-09-04 13:11

MOT test number

899563989804

Result

✓ Passed

MOT #8

2016-10-13 12:06

MOT test number

975441446835

Result

✓ Passed

Advice Front Tyre worn close to the legal limit n/s and o/s (4.1.E.1)

**MOT #7** 2016-10-13 12:06**MOT test number** 472408570133**Result** ✗ Failed**Pass with rectification** Headlamp aim too low n/s and o/s (1.8)**Advice** Front Tyre worn close to the legal limit n/s and o/s (4.1.E.1)**Pass with rectification** Windscreen washer provides insufficient washer liquid n/s and o/s (8.2.3)**MOT #6** 2015-09-09 14:49**MOT test number** 455539764491**Result** ✓ Passed**MOT #5** 2014-09-10 15:11**MOT test number** 397733854483**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2013-09-07 11:51**MOT test number** 495360853281**Result** ✓ Passed**MOT #3** 2013-09-07 11:13**MOT test number** 299290953235**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #2** 2013-02-27 12:02**MOT test number** 178798553427**Result** ✓ Passed



MOT #1	2013-02-27 12:02
MOT test number	887068353015
Result	✗ Failed
Pass with rectification	Front registration plate deteriorated (6.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
9 October 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	9 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2020-01-01
Current registration	XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-03-23
Last registration	2023-10-10
Complete history	See info



Registration #1	2010-03-23	26 mi
Registration #2	2013-02-27	62.818 mi
Registration #3	2013-09-07	71.145 mi
Registration #4	2013-09-07	71.145 mi
Registration #5	2014-09-10	84.191 mi
Registration #6	2015-09-09	95.141 mi
Registration #7	2016-10-13	115.056 mi
Registration #8	2016-10-13	115.056 mi
Registration #9	2016-10-13	115.056 mi
Registration #10	2016-10-13	115.056 mi
Registration #11	2016-10-13	115.056 mi
Registration #12	2016-10-13	115.056 mi
Registration #13	2016-10-13	115.056 mi
Registration #14	2016-10-13	115.056 mi
Registration #15	2016-10-13	115.056 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1404 mm
Length	4256 mm
Wheel base	2578 mm
Kerb weight	1318 kg
Max. allowed weight	1790 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	CDL 022456