





report date: 2024-03-29

#### General information

Make	FIAT
Model	PUNTO MULTIAIR LOUNGE
Colour	White
Year of manufacture	2012
Top speed	124 mph
0 - 60 mph	8.5 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	135 BHP
Max. torque	206 Nm at 1.750 rpm
Engine capacity	1.368 сс
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	61.4 mpg
Consumption combined	50.4 mpg
CO2 emission	129 g/km
CO2 label	D



CarCheck.co.uk page 1/13



report date: 2024-03-29

## Internet history

#### Entry 1

Date	2021-12-18	
Pictures	1	
Listing price	View report	



source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

N/I	$\alpha$		IIC.	t۸	r\/
101	•		115	w	ıv
	•	Γh			. ,

MOT expiry date	2025-01-10
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	24
Total items failed	6

MOT #15		2023-12-13 10:42
MOT test	number	364331377984
Result		✓ Passed
Next exp	ry date	2025-01-10
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Exhaust silencer slightly loose outer case corroded (8.1.1 (b) (i))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Seat belt buckle slightly damaged outer case broken (7.1.2 (d))	
Minor	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b)	(i))

MOT #14		2022-12-20 13:06
MOT test	number	167062167875
Result		✓ Passed
Advice	Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))	
Advice	Rear exhaust back box corroded	
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

**MOT #13** 2022-12-20 11:39 **MOT test number** 562389495647 Result × Failed **Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i)) Offside Rear Coil spring corroded (5.3.1 (b) (i)) Advice Advice Offside Front Coil spring corroded (5.3.1 (b) (i)) Fail Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i)) **Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i)) Advice Nearside Front Coil spring corroded (5.3.1 (b) (i)) **Advice** Rear exhaust back box corroded

MOT #12	2022-01-11 12:10
MOT test number	714363323824
Result	✓ Passed
MOT #11	2021-09-22 09:44
MOT test number	661906721327
Result	✓ Passed
MOT #10	2021-09-21 09:15
MOT test number	349761997823
Result	<b>×</b> Failed
Fail Windscreen washer not working (3.5 (a))	

MOT #9	2021-01-04 13:05
MOT test number	383827438640
Result	<b>✓</b> Passed
Advice Rear exhaust corroded	

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT test number

Result

Advice Nearside Rear Nail in tyre

Advice Nearside Rear Seat belt buckle slightly damaged (7.1.2 (d))

MOT test number

Result

Pass with rectification

Front Windscreen washer not working (3.5 (a))

Advice

Nearside Rear Nail in tyre

Advice

Nearside Rear Seat belt buckle slightly damaged (7.1.2 (d))

MOT #6

MOT test number

Result

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT test number

Result

Pass with rectification

Nearside Front Headlamp aim too high (4.1.2 (a))

Advice

Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #4 2018-01-04 14:58

MOT test number 444988373642

Result ✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #3 2016-12-22 17:01 **MOT test number** 257700740534 Result ✓ Passed MOT #2 2016-12-22 17:01 644087536139 **MOT test number X** Failed Result **Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Pass with rectification Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #1	2016-01-08 10:11
MOT test number	856895607118
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

# Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	10 January 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

## Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report I	
THE PARTY OF THE P	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-12-31
Last registration	2023-12-13
Complete history	See info



Registration #1	2012-12-31	20 mi
Registration #2	2016-01-08	19.742 mi
Registration #3	2016-12-22	29.379 mi
Registration #4	2016-12-22	29.379 mi
Registration #5	2018-01-04	35.441 mi
Registration #6	2018-12-17	41.829 mi
Registration #7	2018-12-17	41.829 mi
Registration #8	2019-12-31	48.991 mi
Registration #9	2019-12-31	48.991 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.177 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1155 kg
Max. allowed weight	1715 kg

# Additional information

Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13

**Engine number** 

1710660