





report date: 2024-03-28

General information

Make	FIAT
Model	QUBO MULTIJET MYLIFE DUALOGIC
Colour	Blue
Year of manufacture	2012
Top speed	96 mph
0 - 60 mph	13.6 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	75 BHP
Max. torque	190 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	76.4 mpg
Consumption combined	68.9 mpg
CO2 emission	107 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2022-02-23

Pictures 3

Listing price <u>View report</u>







source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2025-03-04
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	22
Total items failed	0

MOT #11		2024-03-05 15:00
MOT test	number	869982211981
Result		✓ Passed
Next expi	ry date	2025-03-04
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a	a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #10		2024-02-29 15:06
MOT test	number	560449007414
Result		× Failed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
MAJOR	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor (2.1.3 (g)	Offside Front Steering rack gaiter damaged or deteriorated, but preventing th	e ingress of dirt
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
MAJOR	Offside Front Coil spring mounting damaged and seriously weakened (5.3.1 (b) (i))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #9 2023-02-16 10:17

MOT test number 516048003836

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge STORNG ADVICE (5.2.3 (e))

Minor Offside Obligatory mirror slightly damaged (3.3 (b) (i))

Advice Front NOISE FROM SUSPENSION

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #8 2022-02-28 15:44

MOT test number 520700602545

Result ✓ Passed

MOT #7 2022-02-25 17:14

MOT test number 570346631920

Result X Failed

MAJOR Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #6 2021-03-04 15:13

MOT test number 666328114818

Result

Passed

Minor Offside Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5 2020-01-16 16:43

MOT test number 477609566518

Result ✓ Passed

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened Both front inner faces (1.1.14

(a) (ii))

MOT #4 2018-01-08 16:19

MOT test number 320947439643

MOT #3 2016-10-13 16:09

MOT test number 215035348409

Result \rightarrow Passed

MOT #2 2015-10-01 13:45

MOT test number 248202764429

Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #1 2014-08-28 12:35

MOT test number 549180644270

Result ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	4 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12




report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	

THE STATE OF THE S	
THE STATE OF THE S	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	NK SIK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-01-20
Last registration	2024-03-05
Complete history	See info



Registration #1	2012-01-20	25 mi
Registration #1	2012-01-20	25 1111
Registration #2	2014-08-28	16.165 mi
Registration #3	2015-10-01	35.715 mi
Registration #4	2016-10-13	54.523 mi
Registration #5	2018-01-08	73.670 mi
Registration #6	2020-01-16	81.385 mi
Registration #7	2021-03-04	84.465 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 ea
Registration #11		11.177 mi
Registration #12		11.777 es
Registration #13		D.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Dimensions & weight

Width	1716 mm
Height	1721 mm
Length	3595 mm
Wheel base	2513 mm
Kerb weight	1180 kg
Max. allowed weight	1710 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	4639928

CarCheck.co.uk page 12/12