



UK

LG060FR

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	GOLF
Colour	Blue
Year of manufacture	2006
Gearbox	-

Engine & fuel consumption

Engine capacity	1.980 cc
Fuel type	Petrol



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-02-27
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-10-19
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	12
Total items failed	2

MOT #5	2023-10-20 07:30
MOT test number	604817561220
Result	✓ Passed
Next expiry date	2024-10-19
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #4	2023-10-10 10:37
MOT test number	832832567503
Result	✗ Failed
Advice	Exhaust noisy (8.1.1 (a))
Fail	Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

MOT #3	2022-10-12 13:06
MOT test number	976237272069
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #2	2021-06-26 07:59
MOT test number	600997575499
Result	✓ Passed

MOT #1	2020-06-24 09:28
MOT test number	709101097017
Result	✓ Passed
<div><div>Advice</div> Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))</div> <div><div>Advice</div> Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))</div> <div><div>Advice</div> Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))</div> <div><div>Advice</div> Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))</div> <div><div>Advice</div> Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))</div> <div><div>Advice</div> Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
19 October 2024

Tax status		Valid until 1 April
Days left		337
MOT expiry date		19 October 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2006-06-01
Last registration	2023-10-20
Complete history	See info



Registration #1	2006-06-01	24 mi
Registration #2	2020-06-24	57.460 mi
Registration #3	2021-06-26	62.042 mi
Registration #4	2022-06-28	65.277 mi
Registration #5	2022-06-28	65.277 mi
Registration #6	2022-06-28	65.277 mi
Registration #7	2023-10-20	65.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Additional information

Number of seats	5
Engine number	NOT KNOWN