






report date: 2024-03-29

General information

Make	RENAULT
Model	KANGOO SL 17DCI 70
Colour	White
Year of manufacture	-
Top speed	91 mph
0 - 60 mph	16.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	65 BHP
Max. torque	160 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-01-21

Pictures 9

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/13



MX52GKG report date: 2024-03-29

MOT history

MOT #16	2018-12-08 09:30
MOT test number	540407692515
Result	✓ Passed
Next expiry date	2020-01-06
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #15	2017-12-16 14:27
MOT test number	478729933783
Result	✓ Passed
Advice Nearside Front Nail in tyre	
Advice Oil leak	

MOT #14	2017-01-07 14:27
MOT test number	480499519706
Result	✓ Passed
Advice Nearside Front brake disc worn, pitted or scored, but not seriously weak Advice Offside Front brake disc worn, pitted or scored, but not seriously weak	

MOT #13	2015-03-23 09:04
MOT test number	978772485098
Result	✓ Passed

MOT #12	2014 02 25 10 21
MOT #12	2014-02-25 10:31
MOT test number	456166054009
Result	✓ Passed
Notice Play in steering rack inner joint(s)	

CarCheck.co.uk page 3/13



MX52GKG report date: 2024-03-29

MOT #11 2013-08-09 08:52

MOT test number 577411423248

Result ✓ Passed

Notice Engine covers fitted obscuring some components in the engine bay

Advice Offside Track rod end ball joint has slight play (2.2.B.1f)

Notice Oil leak

Advice Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

MOT #10 2013-08-08 15:56

MOT test number 445090223225

Result X Failed

Advice Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

Notice Engine covers fitted obscuring some components in the engine bay

Fail Nearside Track rod end ball joint has excessive play (2.2.B.1f)

Fail Nearside Front Anti-roll bar linkage rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Advice Offside Track rod end ball joint has slight play (2.2.B.1f)

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Notice Oil leak

Fail Offside Front Anti-roll bar linkage rubber mounting deteriorated resulting in excessive movement (2.4.G.2)

Fail Offside front brake excessively fluctuating (3.7.B.3)

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #9 2012-02-06 16:25 585927732013 **MOT** test number Result ✓ Passed Notice Both front link bars in poor condition. Notice Just acceptable movement in n/s headlamp. Notice Clutch release bearing noisey. Notice Surface corrosion on o/s/f brakedisc. Notice Airbag warning lamp on. Notice N/s seatbelt webbing slightly damaged. Notice Front of vehicle damaged. Notice Oil leaks around engine.

MOT #8 2012-02-06 10:16 **MOT** test number 286067132010 × Failed Result **Notice** Surface corrosion on o/s/f brakedisc. Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2) Notice Airbag warning lamp on. Notice N/s seatbelt webbing slightly damaged. Notice Front of vehicle damaged. Oil leaks around engine. Notice Notice Both front link bars in poor condition. Fail Emissions not tested (7.0) Notice Just acceptable movement in n/s headlamp. Notice Clutch release bearing noisey.

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #7	2010-11-03 16:40
MOT test number	894947500392
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #6		2009-11-05 15:49
MOT test	number	784899009396
Result		✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #5	2008-11-07 15:16
MOT test number	263092718318
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

MOT #4 2008-11-05 09:39

MOT test number 551800518362

Result X Failed

Fail Offside Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Front position lamp(s) not working (1.1.A.3b)

Fail Nearside Headlamp insecure (1.7.3)

Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Nearside Front front brake juddering severely (3.7.A.2b)

Fail Centre Stop lamp not working (1.2.1b)

Advice Offside Front front brake juddering slightly (3.7.A.2b)

Fail Nearside Registration plate lamp not working (1.1.5c)

Fail Nearside Headlamp aim too high and too far to the right. (1.8)

MOT #3 2007-10-10 10:49

MOT test number 244323687294

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside front brake grabbing slightly (3.7.A.2b)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front brake disc slightly pitted (3.5.1h)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2006-11-09 17:09

MOT test number 482933916399

Result / Passed

CarCheck.co.uk page 7/13



report date: 2024-03-29

MOT #1 2005-10-15 12:22

MOT test number 323688485221

Result ✓ Passed

CarCheck.co.uk page 8/13



report date: 2024-03-29

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/13



Owner history

MX52GKG

report date: 2024-03-29

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RE have? Check it in the premium report and see all owner registrations. Download the full report here .	NAULT
THE STATE OF THE S	

THE STATE OF THE S	

Plate changes

See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	SIES UK
Plate since	
Current registration	NK UK
Plate since	

More info >

More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2002-10-14
Last registration	2018-12-08
Complete history	See info



Registration #1	2002-10-14	18 mi
Registration #2	2005-10-15	48.286 mi
Registration #3	2006-11-09	57.551 mi
Registration #4	2007-10-10	71.092 mi
Registration #5	2008-11-07	81.411 mi
Registration #6	2009-11-05	90.364 mi
Registration #7	2010-11-03	96.440 mi
Registration #8	2012-02-06	100.450 mi
Registration #9	2012-02-06	100.450 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		9.777 es

More info >

CarCheck.co.uk page 12/13



MX52GKG report date: 2024-03-29

Car features

50225	Air conditionin
50295	
50482	
50501	
50566	
60567	
50569	

		_		
Dim	ensior	יכ צי	MAIG	ht
ווווט	CHOIDE	IS CX	WCIU	IIIL

Width	2031 mm
Height	1835 mm
Length	4035 mm
Kerb weight	1055 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	3
Engine number	D269787

CarCheck.co.uk page 13/13