





report date: 2024-03-29

General information

Make	RENAULT
Model	TRAFIC LL29 DCI S/R W/V
Colour	Silver
Year of manufacture	2012
Top speed	99 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	300 Nm at 1.500 rpm
Engine capacity	1.996 сс
Cylinders	4
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	39.8 mpg
Consumption combined	35.8 mpg



CarCheck.co.uk page 1/13



YH12HFO

report date: 2024-03-29

Internet history

Entry 1

Date 2022-01-13

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-03-14
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	6
Total items failed	19

MOT #17	2024-03-15 16:26
MOT test number	674601083454
Result	✓ Passed
Next expiry date	2025-03-14
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #	16	2024-03-06 09:02
MOT te	est number	449852184098
Result		X Failed
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))	
Fail	Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Fail	Front Registration plate missing (0.1 (a))	
Advid	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail	Nearside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))
Fail	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #15	2023-03-10 15:29
MOT test number	726650344575
Result	✓ Passed

CarCheck.co.uk page 3/13



MOT #14 2022-03-05 08:34

MOT test number 947174282613

MOT #13 2021-02-24 14:59

MOT test number 412441289542

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #12 2021-02-23 11:17

MOT test number 965239723767

Result X Failed

Fail Offside Front Macpherson strut mounting damaged and seriously weakened (5.3.3 (b) (i))

Fail Offside Rear Seat belt buckle not functioning as intended (7.1.2 (d))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Hazard warning switch inoperative (4.4.2 (a) (ii))

MOT #11 2020-02-21 14:34

MOT test number 109817788829

MOT #10 2020-02-21 09:34

MOT test number 421355172453

Result X Failed

Fail Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #9 2019-02-22 11:39

MOT test number 881136658947

Result
✓ Passed

CarCheck.co.uk page 4/13



MOT #8 2019-02-22 09:37

MOT test number 315038951465

Result X Failed

Fail Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #7 2018-02-26 15:52

MOT test number 958666479279

Result \(\sqrt{Passed} \)

Advice Nearside Front Play in steering rack inner joint(s)

MOT #6 2018-02-26 11:21

MOT test number 975702694191

Result X Failed

Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Offside Front Macpherson strut has excessive movement at the upper attachment (2.5.A.1c)

Fail Offside rear parking brake recording little or no effort (3.7.B.6a)

Fail Parking brake: efficiency below requirements (3.7.B.7)

Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

Fail Nearside rear parking brake recording little or no effort (3.7.B.6a)

Advice Nearside Front Play in steering rack inner joint(s)

MOT #5 2017-03-07 11:38

MOT test number 599609781327

Result ✓ Passed

CarCheck.co.uk page 5/13



MOT #4 2016-03-29 14:37

MOT test number 115412102098

Result
✓ Passed

MOT #3 2016-03-29 14:37

MOT test number 676196857991

Result × Failed

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #2 2015-03-28 10:02

MOT test number 487147285040

Result ✓ Passed

MOT #1 2015-03-28 10:02

MOT test number 677807885011

Result × Failed

Pass with rectification Offside Headlamp not working on dipped beam (1.7.5a)

CarCheck.co.uk page 6/13



Tax & MOT check



Days left306MOT expiry date14 March 2025

Full MOT history See MOT history

CarCheck.co.uk page 7/13



YH12HFO

report date: 2024-03-29

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



YH12HFO

report date: 2024-03-29

Owner	history
-------	---------

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full		ULT

	More info	>
Plate changes		
See in this check if this RENAULT had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2012-03-31
Last registration	2024-03-15
Complete history	See info



Registration #1	2012-03-31	28 mi
Registration #2	2015-03-28	43.786 mi
Registration #3	2016-03-29	50.532 mi
Registration #4	2016-03-29	50.532 mi
Registration #5	2017-03-07	53.576 mi
Registration #6	2018-02-26	56.556 mi
Registration #7	2018-02-26	56.561 mi
Registration #8	2019-02-22	59.087 mi
Registration #9	2019-02-22	59.087 mi
Registration #10		11.177 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.177 mg

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

				~			
ונו	men:	CIOT	nc -	λ.	WAI	α	ht.
וט	пеп	SIUI	13	CX.	$VV \subset I$	ш	TTU.

Width	1904 mm
Height	1955 mm
Length	5182 mm
Kerb weight	1926 kg
Max. allowed weight	3005 kg

Additional information

Fuel tank capacity	90
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	6
Engine number	C012672

CarCheck.co.uk page 13/13