




report date: 2024-03-28

## General information

Make	VOLVO
Model	XC70 D5 SE LUX AWD
Colour	Gold
Year of manufacture	2015
Top speed	130 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	220 BHP
Max. torque	440 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	54.3 mpg
Consumption combined	48.7 mpg
CO2 emission	153 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-10-29
Pictures	16
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT expiry date</b>	2024-10-26
<b>MOT pass rate</b>	78 %
<b>MOT passed</b>	7
<b>Failed MOT tests</b>	2
<b>Total advice items</b>	7
<b>Total items failed</b>	3

**MOT #9** 2023-10-25 08:50**MOT test number** 370708961539**Result** Passed**Next expiry date** 2024-10-26**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #8** 2022-10-24 14:56**MOT test number** 177252587080**Result** Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))**MOT #7** 2021-10-27 10:11**MOT test number** 104278965936**Result** Passed

**MOT #6** 2021-10-22 12:24**MOT test number** 654852599423**Result** ✗ Failed**Fail** Bonnet primary retaining device excessively deteriorated (3.1 (c))**MOT #5** 2021-03-25 16:07**MOT test number** 955606729326**Result** ✓ Passed**MOT #4** 2020-07-28 08:59**MOT test number** 418009331676**Result** ✓ Passed**MOT #3** 2020-07-21 13:58**MOT test number** 741452426124**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Nail in tyre**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #2** 2019-06-28 09:18**MOT test number** 825849893062**Result** ✓ Passed**MOT #1** 2018-07-06 08:56**MOT test number** 409064728585**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
26 October 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	33
<b>MOT expiry date</b>	26 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-07-20
Last registration	2023-10-25
Complete history	<a href="#">See info</a>



Registration #1	2015-07-20	27 mi
Registration #2	2018-07-06	21.057 mi
Registration #3	2019-06-28	25.387 mi
Registration #4	2020-07-21	28.900 mi
Registration #5	2020-07-28	28.901 mi
Registration #6	2021-03-25	30.326 mi
Registration #7	2023-10-25	30.327 mi
Registration #8	2023-10-25	30.327 mi
Registration #9	2023-10-25	30.327 mi
Registration #10	2023-10-25	30.327 mi
Registration #11	2023-10-25	30.327 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2119 mm
Height	1604 mm
Length	4838 mm
Wheel base	2815 mm
Kerb weight	1884 kg
Max. allowed weight	2400 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1623111