



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN TDI SPORT 5 STR
Colour	Blue
Year of manufacture	-
Top speed	122 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	46.3 mpg





Internet history

Entry 1

Date	2021-07-14
Pictures	1
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #21	2021-08-10 16:08
MOT test number	550122482731
Result	✓ Passed
Next expiry date	2022-08-10
Advice	Front tyres x 2 edges worn

MOT #20	2021-08-10 16:08
MOT test number	791503053450
Result	✗ Failed
Pass with rectification	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
Advice	Front tyres x 2 edges worn

MOT #19	2021-07-30 10:40
MOT test number	977577446211
Result	✗ Failed
Advice	Offside Rear brake discs back plate corroded
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush half split (5.3.4 (a) (i))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Advice	Front both brake discs back plates corroded
Fail	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (ii))
Fail	Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt and track rod ball joint has play (2.1.3 (g) (ii))
Fail	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
Advice	Front both tyres wearing out on edges

**MOT #18**

2020-07-21 11:10

MOT test number

810811579684

Result

✓ Passed

Advice Offside Rear Road wheel slightly distorted inner rim (5.2.2 (c) (i))**Advice** Oil leak, but not excessive from transmission (8.4.1 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view stonechipped (3.2 (a) (i))**Advice** Nearside Front Road wheel slightly distorted inner rim (5.2.2 (c) (i))**Advice** Oil leak, but not excessive from engine (8.4.1 (a) (i))**MOT #17**

2020-07-17 16:45

MOT test number

878912234130

Result

✗ Failed

Advice Nearside Front Road wheel slightly distorted inner rim (5.2.2 (c) (i))**Advice** Oil leak, but not excessive from engine (8.4.1 (a) (i))**Fail** Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))**Minor** Windscreen damaged but not adversely affecting driver's view stonechipped (3.2 (a) (i))**Advice** Offside Rear Road wheel slightly distorted inner rim (5.2.2 (c) (i))**Advice** Oil leak, but not excessive from transmission (8.4.1 (a) (i))**MOT #16**

2019-07-12 10:44

MOT test number

741754859813

Result

✓ Passed

MOT #15

2018-07-25 08:20

MOT test number

286837813264

Result

✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement bottom arm rear bush (5.3.4 (a) (i))

**MOT #14** 2017-08-11 09:40**MOT test number** 185201011258**Result** ✓ Passed**Advice** Brake hose slightly deteriorated both rear (3.6.B.4d)**Advice** Both front tyres void on outer edges**Advice** Suspension arm rubber mounting deteriorated but not resulting in excessive movement both front lower (2.4.G.2)**MOT #13** 2016-09-09 15:12**MOT test number** 814104297679**Result** ✓ Passed**Advice** Offside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt pin hole (2.5.C.1a)**Advice** Offside Rear Direction indicator slightly discoloured slightly white (1.4.A.2f)**MOT #12** 2016-09-09 11:54**MOT test number** 581234155134**Result** ✗ Failed**Fail** Nearside Outer Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Offside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt pin hole (2.5.C.1a)**Advice** Offside Rear Direction indicator slightly discoloured slightly white (1.4.A.2f)**MOT #11** 2015-09-14 15:50**MOT test number** 899663620900**Result** ✓ Passed**MOT #10** 2014-09-18 14:32**MOT test number** 519941464249**Result** ✓ Passed**Notice** Traction control light on

**MOT #9** 2014-09-18 10:56**MOT test number** 328311964432**Result** ✗ Failed**Fail** Offside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)**Notice** Traction control light on**MOT #8** 2013-09-26 09:34**MOT test number** 228119763298**Result** ✓ Passed**MOT #7** 2012-09-20 13:09**MOT test number** 318814062225**Result** ✓ Passed**MOT #6** 2012-09-20 11:15**MOT test number** 677474262272**Result** ✗ Failed**Fail** Direction indicator incorrect colour (1.4.A.2f)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #5** 2011-09-15 15:02**MOT test number** 107908851214**Result** ✓ Passed**Advice** Offside Front constant velocity joint gaiter deteriorated (2.5.C.1a)**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Nearside Front constant velocity joint gaiter deteriorated (2.5.C.1a)**Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)



MOT #4	2010-09-23 12:49
MOT test number	282456760226
Result	✓ Passed
MOT #3	2009-09-23 14:05
MOT test number	284966469279
Result	✓ Passed
MOT #2	2009-09-23 14:05
MOT test number	612146569253
Result	✗ Failed
<div>Pass with rectification</div> Nearside Front Wheel bolt(s) missing (4.2.A.1e)	
MOT #1	2008-09-26 12:51
MOT test number	714340678220
Result	✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 FN55KFW
Plate since	2019-06-29
Current registration	 FN55KFW
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-09-28
Last registration	2021-08-10
Complete history	See info



Registration #1	2005-09-28	11 mi
Registration #2	2008-09-26	19.645 mi
Registration #3	2009-09-23	28.637 mi
Registration #4	2010-09-23	36.323 mi
Registration #5	2011-09-15	46.247 mi
Registration #6	2012-09-20	55.232 mi
Registration #7	2012-09-20	55.232 mi
Registration #8	2013-09-26	63.824 mi
Registration #9	2014-09-18	70.926 mi
Registration #10	2014-09-18	70.926 mi
Registration #11	2015-09-14	78.706 mi
Registration #12	2016-09-20	86.557 mi
Registration #13	2017-09-20	94.408 mi
Registration #14	2018-09-20	102.259 mi
Registration #15	2019-09-20	110.110 mi
Registration #16	2020-09-20	117.961 mi
Registration #17	2021-08-10	125.812 mi
Registration #18	2021-08-10	125.812 mi
Registration #19	2021-08-10	125.812 mi
Registration #20	2021-08-10	125.812 mi
Registration #21	2021-08-10	125.812 mi
Registration #22	2021-08-10	125.812 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1561 kg
Max. allowed weight	2260 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats

7

Engine number

BKD 273117