



GF06BNA


report date: 2024-03-29

General information

Make	JAGUAR
Model	XK CONVERTIBLE
Colour	Blue
Year of manufacture	2006
Top speed	155 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	294 BHP
Max. torque	411 Nm at 4.100 rpm
Engine capacity	4.196 cc
Cylinders	8
Fuel type	Petrol
Consumption city	16.5 mpg
Consumption extra urban	33.6 mpg
Consumption combined	25.0 mpg
CO2 emission	269 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-07-16
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-10
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	31
Total items failed	5

MOT #202024-04-03 15:35

MOT test number111471789926

Result✓ Passed

Next expiry date2025-04-10

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Rear Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #192024-04-03 10:03

MOT test number431467925724

Result✗ Failed

Advice Offside Rear Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Front Nail in tyre

Fail Offside Front Service brake lagging in operation (1.2.1 (d))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #182023-03-31 15:29

MOT test number778610634507

Result✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17**

2023-03-31 13:21

MOT test number

841137126173

Result

✗ Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Exhaust mounting defective (6.1.2 (a))**MOT #16**

2022-04-11 12:04

MOT test number

119726635233

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge very close / Recommend replacement (5.2.3 (e))**Advice** Vehicle fitted with sill covers**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Minor** Offside Rear Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Rear Suspension components corroded / underseal applied**Minor** Nearside Rear Direction indicator lens defective which has no effect on emitted light Condensation behind lens (4.4.1 (b) (i))**MOT #15**

2021-04-07 09:01

MOT test number

352845406449

Result

✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Vehicle fitted with sill covers

**MOT #14** 2020-01-21 10:13**MOT test number** 833718286530**Result** ✓ Passed**Advice** Vehicle fitted with sill covers**Advice** Nearside Front Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #13** 2019-01-10 09:56**MOT test number** 521297792057**Result** ✓ Passed**MOT #12** 2018-01-26 12:31**MOT test number** 277697460477**Result** ✓ Passed**MOT #11** 2017-01-09 10:20**MOT test number** 792466158570**Result** ✓ Passed**MOT #10** 2016-01-25 15:39**MOT test number** 119284600395**Result** ✓ Passed**Advice** Engine covers and under tray fitted**MOT #9** 2016-01-19 15:37**MOT test number** 395925261211**Result** ✗ Failed**Fail** Nearside Front Headlamp not working on main beam (1.7.5a)**Advice** Engine covers and under tray fitted**Fail** Nearside Rear Inner Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt tie bar inner balljoint (2.4.G.2)

**MOT #8** 2014-12-23 10:31**MOT test number** 499807654448**Result** ✓ Passed**MOT #7** 2013-12-23 10:04**MOT test number** 895847153338**Result** ✓ Passed

- Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Offside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Nearside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)

MOT #6 2013-01-16 11:54**MOT test number** 418406513062**Result** ✓ Passed

- Advice** Nearside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice** Nearside Rear Shock absorber has a slightly worn bush (2.7.4)
- Notice** Oil leak
- Notice** Rear pads low
- Advice** Offside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice** Offside Rear Shock absorber has a slightly worn bush (2.7.4)
- Notice** Engine covers fitted obscuring some components in the engine bay

MOT #5 2012-01-23 16:49**MOT test number** 265773322054**Result** ✓ Passed



MOT #4 2011-06-21 11:52

MOT test number 665792271164

Result ✓ Passed

MOT #3 2010-06-23 16:47

MOT test number 402324470107

Result ✓ Passed

MOT #2 2010-03-25 11:03

MOT test number 101584080490

Result ✓ Passed

MOT #1 2009-03-24 16:46

MOT test number 590483389056

Result ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
10 April 2025

Tax status	Valid until 1 November
Days left	186
MOT expiry date	10 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-03-25
Last registration	2024-04-03
Complete history	See info



Registration #1	2006-03-25	25 mi
Registration #2	2009-03-24	27.331 mi
Registration #3	2010-03-25	36.460 mi
Registration #4	2010-06-23	37.246 mi
Registration #5	2011-06-21	40.049 mi
Registration #6	2012-01-23	42.150 mi
Registration #7	2013-01-16	53.298 mi
Registration #8	2013-12-23	65.897 mi
Registration #9	2014-12-23	79.608 mi
Registration #10	2016-01-19	88.107 mi
Registration #11	2016-01-25	88.117 mi
Registration #12	2016-01-25	88.117 mi
Registration #13	2016-01-25	88.117 mi
Registration #14	2016-01-25	88.117 mi
Registration #15	2016-01-25	88.117 mi
Registration #16	2016-01-25	88.117 mi
Registration #17	2016-01-25	88.117 mi
Registration #18	2016-01-25	88.117 mi
Registration #19	2016-01-25	88.117 mi
Registration #20	2016-01-25	88.117 mi
Registration #21	2016-01-25	88.117 mi
Registration #22	2016-01-25	88.117 mi

More info >



Dimensions & weight

Width	1892 mm
Height	1329 mm
Length	4791 mm
Wheel base	2752 mm
Kerb weight	1815 kg
Max. allowed weight	2075 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	06032910285G