





General information

Make	VOLKSWAGEN
Model	PASSAT GTE ADVANCE DSG
Colour	White
Year of manufacture	2018
Top speed	140 mph
0 - 100 km/h	7.6 seconds
0 - 60 mph	7.6 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	115 kW / 157 HP / 215 BHP	0 < 101 A
Max. torque	400 Nm at 1.600 rpm	101 - 120 ^B _C
Engine capacity	1.395 cc	121 - 140 P
Cylinders	4	141 - 165 ^F _G
Fuel type	Hybrid / Electric	166 - 185
Consumption combined	166.2 mpg	186 - 225 J
CO2 emission	40 g/km	225+ L
CO2 label	А	





Internet history

Entry 2

Date

Listing price

Pictures

10

2022-06-13

View report



source: autoonline.co.uk

Entry 1

Date

Pictures

Listing price

2022-05-23 12 <u>View report</u>







source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-22
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	13
Total items failed	1

MOT #5 202	24-04-23 13:01
MOT test number	396116410416
Result	🗸 Passed
Next expiry date	2025-04-22
Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Minor Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #4	2023-04-20 11:45
MOT test number	221089874999
Result	✓ Passed

MOT #3	2022-03-31 15:48
MOT test	number 218053649505
Result	✓ Passed
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))





MOT #2		2022-03-30 10:04
MOT test	number	973618438465
Result		🗙 Failed
Advice	Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened	l (1.1.14 (a) (ii))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened	(1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakene	ed (1.1.14 (a) (ii))
Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords and has 2 nails in it (5.2.3 (d) (i))		
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakene	ed (1.1.14 (a) (ii))

MOT #1	2021-04-01 10:47
MOT test number	281380189422
Result	✓ Passed



Tax & MOT check

✓ Taxed	√ МОТ
Tax due: 1 June 2024	Expires: 22 April 2025
Tax status	Valid until 1 June
Days left	32
MOT expiry date	22 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	В
First licence fee (12 months)	£ 0,00,-
Standard rate (12 months)	£ 170,00,-
Standard rate (6 months)	£ 93,50,-
Premium rate (12 months)	£ 560,00,-
Premium rate (6 months)	£ 308,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDER
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E CONTROL ON
Date	S.
Category	AMPY
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second sec	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-04-23
Last registration	2024-04-23
Complete history	See info



Registration #1	2018-04-23	25 mi
Registration #2	2021-04-01	42.149 mi
Registration #3	2022-03-30	59.145 mi
Registration #4	2022-03-31	59.145 mi
Registration #5		11.777 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		10.377 est

More info \rightarrow





Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	85%
Children	87%
Pedestrian	66%
Safety systems	76%
Overall rating	80%
Video	see crash video



Dimensions & weight	
Width	1832 mm
Height	1477 mm
Length	4767 mm
Wheel base	2791 mm
Kerb weight	1660 kg
Max. allowed weight	2250 kg
Additional information	
Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
CarCheck.co.uk	page 11

Number of seats	5
Number of axles	2
Engine number	CUKC118668