





report date: 2024-03-29

General information

| Make | MINI |
|---------------------|----------------|
| Model | MINI (R60) ONE |
| Colour | Black |
| Year of manufacture | 2012 |
| Top speed | 107 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 98 BHP |
|-------------------------|---------------------|
| Max. torque | 153 Nm at 3.000 rpm |
| Engine capacity | 1.598 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 38.2 mpg |
| Consumption extra urban | 54.3 mpg |
| Consumption combined | 47.1 mpg |
| CO2 emission | 139 g/km |
| CO2 label | E |



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-08-25

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date | 2024-09-17 |
|--------------------|------------|
| MOT pass rate | 82 % |
| MOT passed | 9 |
| Failed MOT tests | 2 |
| Total advice items | 15 |
| Total items failed | 2 |

| MOT #11 | | 2023-09-18 16:28 |
|-----------|---|------------------|
| MOT test | number | 538510502632 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-09-17 |
| Advice | Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii) |) |
| Advice | Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #10 | | 2022-08-04 14:48 |
|-------------------------|---|------------------|
| MOT test number | | 691843855917 |
| Result | | ✓ Passed |
| | | |
| MOT #9 | | 2022-08-04 14:48 |
| MOT test number | | 685717788092 |
| Result | | X Failed |
| Pass with rectification | Nearside Front Position lamp not working (4.2.1 (a) (ii)) | |

CarCheck.co.uk page 3/12



MOT test number

Result

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake pad(s) wearing thin both (1.1.13 (a) (ii))

Advice Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))

MOT #7

MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2.0mm (5.2.3 (e))

Minor Windscreen damaged but not adversely affecting driver's view stone chip (3.2 (a) (i))


| MOT #5 | 2018-02-13 10:38 |
|-----------------|------------------|
| MOT test number | 969771311660 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2017-02-21 16:11 |
| MOT test number | 512163573195 |
| Result | ✓ Passed |


CarCheck.co.uk page 4/12



LC12SHX

report date: 2024-03-29





CarCheck.co.uk page 5/12



Tax & MOT check



| Tax status | Valid until 1 August |
|------------------|----------------------|
| Days left | 94 |
| MOT expiry date | 17 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | Е |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| | |



Extra MINI salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

| Owner mistory | |
|--|------------------|
| For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report J | |
| *************************************** | |
| | |
| *************************************** | |
| | |
| THE PARTY OF THE P | |
| | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this MINI had different number plates. | |
| Number of plates | , |
| Current registration | UK UK |
| Plate since | |
| Current registration | OK SIE SIE |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 9/12



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 13 |
| First mileage registration | 2012-06-11 |
| Last registration | 2023-09-18 |
| Complete history | See info |



| Registration #1 | 2012-06-11 | 10 mi |
|------------------|------------|-----------|
| Registration #2 | 2015-06-08 | 30.549 mi |
| Registration #3 | 2015-06-08 | 30.549 mi |
| Registration #4 | 2016-09-06 | 32.683 mi |
| Registration #5 | 2017-02-21 | 37.659 mi |
| Registration #6 | 2018-02-13 | 46.237 mi |
| Registration #7 | 2019-02-23 | 56.231 mi |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 10.777 es |

More info >

CarCheck.co.uk page 11/12



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 60567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 84% |
| Children | 83% |
| Pedestrian | 63% |
| Safety systems | 71% |
| Overall rating | 78% |
| Video | see crash video |



Dimensions & weight

| Width | 1789 mm |
|---------------------|---------|
| Height | 1561 mm |
| Length | 4097 mm |
| Wheel base | 2595 mm |
| Kerb weight | 1265 kg |
| Max. allowed weight | 1775 kg |

Additional information

| Fuel tank capacity | 47 |
|-----------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 12/12 |

Number of axles2Engine numberB409J297