





report date: 2024-03-28

General information

| Make | VAUXHALL |
|---------------------|----------------|
| Model | ADAM ENERGISED |
| Colour | Blue |
| Year of manufacture | 2018 |
| Top speed | 102 mph |
| 0 - 60 mph | 14.9 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 69 BHP |
|-------------------------|---------------------|
| Max. torque | 115 Nm at 4.000 rpm |
| Engine capacity | 1.229 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 39.2 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 53.3 mpg |
| CO2 emission | 125 g/km |
| CO2 label | D |



CarCheck.co.uk page 1/11



Internet history

Entry 3

Date 2021-08-23

Pictures 37

Listing price <u>View report</u>









source: yesauto.com

Entry 2

| Date | 2021-08-12 |
|---------------|-------------|
| Pictures | 0 |
| Listing price | View report |

source: heycar.co.uk

Entry 1

| Date | 2021-08-12 |
|---------------|-------------|
| Pictures | 0 |
| Listing price | View report |

source: cargurus.co.uk

CarCheck.co.uk page 2/11



| MOT history |
|-------------|
|-------------|

| MOT expiry date | 2025-04-29 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 4 |
| Failed MOT tests | 1 |
| Total advice items | 4 |
| Total items failed | 1 |

| MOT #5 | 2024-04-17 14:01 |
|--|------------------|
| MOT test number | 122523819043 |
| Result | ✓ Passed |
| Next expiry date | 2025-04-29 |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

| MOT #4 | 2023-04-24 12:04 |
|---|------------------|
| MOT test number | 567607134184 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2022-04-13 10:01 |
| MOT test number | 769663203592 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2021-04-06 13:42 |
| MOT test number | 611557556100 |
| Result | ✓ Passed |
| Advice Nearside Front Tyre slightly damaged outer sidewall (5.2.3 (d) (ii)) | |

CarCheck.co.uk page 3/11



Advice

LL18CWX
report date: 2024-03-28

10poil autor 202 : 00 20

MOT #1

MOT test number

248291149134

Result

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))

Nearside Front Tyre slightly damaged outer sidewall (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 September |
|------------------|-------------------------|
| Days left | 125 |
| MOT expiry date | 29 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |
| | |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date

Category

Type

Damage 2

Date

Category

Type



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| Owner history | |
|--|---|
| For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloaner. | |
| ********* | |
| *************************************** | |
| *************************************** | |
| ******** | |
| | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this VAUXHALL had different number plates. | |
| Mumber of plates | , |
| Current registration | UK NE |
| Plate since | |
| Current registration | AIN |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 8/11



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 9 |
| First mileage registration | 2018-04-30 |
| Last registration | 2024-04-17 |
| Complete history | See info |



| Registration #1 | 2018-04-30 | 25 mi |
|-----------------|------------|-----------|
| Registration #2 | 2021-04-06 | 15.407 mi |
| Registration #3 | 2021-04-06 | 15.407 mi |
| Registration #4 | | 71.777 66 |
| Registration #5 | | 11.777 es |
| Registration #6 | | 71.777 66 |
| Registration #7 | | 11.777 no |
| Registration #8 | | 71.777 66 |
| Registration #9 | | 11.777 es |

More info >

CarCheck.co.uk page 10/11



Safety ratings

| NCAP rating | *** |
|----------------|-----------------|
| Adult | 87% |
| Children | 72% |
| Pedestrian | 65% |
| Safety systems | 81% |
| Overall rating | 79% |
| Video | see crash video |



Dimensions & weight

| Width | 1966 mm |
|---------------------|---------|
| Height | 1483 mm |
| Length | 3698 mm |
| Wheel base | 2311 mm |
| Kerb weight | 1011 kg |
| Max. allowed weight | 1470 kg |

Additional information

| Fuel tank capacity | 38 I |
|--------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | B12XER -19SH7308LWD |

CarCheck.co.uk page 11/11