





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO SE
Colour	Red
Year of manufacture	2015
Top speed	100 mph
0 - 100 km/h	14.3 seconds
0 - 60 mph	15.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	44 kW / 60 HP / 59 BHP
Max. torque	95 Nm at 3.000 rpm
Engine capacity	999 сс
Cylinders	3
Fuel type	Petrol
Consumption city	49.6 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg
CO2 emission	106 g/km
CO2 label	В



CarCheck.co.uk page 1/12



DA65UXZ report date: 2024-03-28

Internet history

Entry 2

Date 2021-07-24

Pictures 5

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date	2021-07-13

Pictures 2

Listing price <u>View report</u>





source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

✓ Passed

м	$\cap T$	history
- 1	\mathbf{c}	IIIJUU

Result

MOT expiry date

. To Texpiry date	2023 03 20
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	8
Total items failed	2
MOT #9	2024-03-27 13:52
MOT test number	210895125683
Result	✓ Passed
Next expiry date	2025-03-28
MOT #8	2023-03-28 07:40
MOT test number	575846748587

2025-03-28

MOT #7	2022-03-19 13:26
MOT test number	641740868303
Result	✓ Passed

MOT #6	2021-03-15 16:35
MOT test number	190086505943
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #5 2020-03-11 16:36

MOT test number 103771723728

Result ✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

(3.3.1 (4) (1)

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #4 2020-03-11 11:54

MOT test number 800846058997

Result X Failed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 2.0mm (5.2.3 (e))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge 3.0mm (5.2.3 (e))

MOT #3 2019-03-11 14:43

MOT test number 442969354394

Result

Passed

MOT #2 2019-03-11 14:43

MOT test number 105708679212

Result ★ Failed

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #1 2018-03-29 07:49

MOT test number 725740934289

Result ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	28 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date
Category

Type

Damage 2

Date

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



DA65UXZ report date: 2024-03-28

Owner history

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many volkswagen have? Check it in the premium report and see all owner registrations. Dow here.	

Plate changes	More info >
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-09-29
Last registration	2024-03-27
Complete history	See info



Registration #1	2015-09-29	11 mi
Registration #2	2018-03-29	19.748 mi
Registration #3	2019-03-11	30.650 mi
Registration #4	2019-03-11	30.650 mi
Registration #5	2020-03-11	37.737 mi
Registration #6	2020-03-11	37.737 mi
Registration #7		11.777 es
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		71.777 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 11/12



DA65UXZ report date: 2024-03-28

Car features

50225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1453 mm
Length	3972 mm
Wheel base	2470 mm
Kerb weight	1067 kg
Max. allowed weight	1540 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	3
CarChaeleeaule	nama 12/12

CarCheck.co.uk page 12/12

Number of seats	5
Number of axles	2
Engine number	CHYA451626