




report date: 2025-02-13

General information

Make	KIA
Model	PRIDE LX
Colour	Red
Year of manufacture	-
Top speed	91 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	64 BHP
Max. torque	131 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol





Internet history

Entry 1

Date	2021-05-22
Pictures	7
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT #16	2020-08-11 14:54
MOT test number	921825353916
Result	✓ Passed
Next expiry date	2021-08-29
Advice	Offside outer sill corroded
Advice	Nearside headlamp beam pattern weak
Advice	Rear axle corroded
Advice	Coil spring corroded all four (5.3.1 (b) (i))
Advice	Exhaust corrosion
Advice	All four tyres cracked and perished

MOT #15	2019-08-28 11:46
MOT test number	260941807717
Result	✓ Passed
Advice	Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
Minor	Nearside Headlamp reflector slightly defective (4.1.1 (b) (i))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #14	2018-08-15 14:47
MOT test number	654915378530
Result	✓ Passed
Advice	Advise surface corrosion on suspension and braking components



MOT #13 2017-08-21 14:52

MOT test number 743766053533

Result ✓ Passed

Advice Nearside Lower Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Vehicle corroded on various underside suspension components

MOT #12 2016-08-30 13:30

MOT test number 535116620269

Result ✓ Passed

Advice Corrosion on rear subframe and brake backplates

Advice Nearside Headlamp has a product on the light source but not seriously reducing light output (1.7.5a)

Advice Offside Headlamp has a product on the light source but not seriously reducing light output (1.7.5a)

MOT #11 2015-08-25 13:04

MOT test number 928067335285

Result ✓ Passed

Notice Advise tyres showing signs of perishing

Notice Advise rear suspension components corroded

MOT #10 2014-08-20 15:20

MOT test number 527872834200

Result ✓ Passed

MOT #9 2013-08-21 13:59

MOT test number 299723733216

Result ✓ Passed

Notice Advise surface corrosion on suspension and braking components



MOT #8 2012-08-23 12:45

MOT test number 619016232244

Result ✓ Passed

MOT #7 2012-08-23 12:45

MOT test number 157336632244

Result ✗ Failed

Pass with rectification Offside Front position lamp(s) not working (1.1.A.3b)

MOT #6 2011-08-23 14:46

MOT test number 675445631283

Result ✓ Passed

MOT #5 2010-08-24 11:57

MOT test number 461356130254

Result ✓ Passed

MOT #4 2009-08-17 10:09

MOT test number 361049129223

Result ✓ Passed

MOT #3 2008-08-11 13:01

MOT test number 582684728237

Result ✓ Passed

MOT #2 2007-08-16 12:28

MOT test number 202428927240

Result ✓ Passed



MOT #1	2006-08-17 14:33
MOT test number	500329026249
Result	✓ Passed




Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Due to strict data protection laws, we cannot and do not provide the personal details of a vehicle's owner. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	YX11
Plate since	2015-05-29
Current registration	YX11
Plate since	2015-05-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	1995-08-15
Last registration	2020-08-11
Complete history	See info



Registration #1	1995-08-15	13 mi
Registration #2	2006-08-17	11.926 mi
Registration #3	2007-08-16	12.475 mi
Registration #4	2008-08-11	13.052 mi
Registration #5	2009-08-17	13.243 mi
Registration #6	2010-08-24	13.452 mi
Registration #7	2011-08-23	13.835 mi
Registration #8	2012-08-23	14.233 mi
Registration #9	2013-08-21	14.518 mi
Registration #10	2014-08-21	14.803 mi
Registration #11	2015-08-21	15.088 mi
Registration #12	2016-08-21	15.373 mi
Registration #13	2017-08-21	15.658 mi
Registration #14	2018-08-21	15.943 mi
Registration #15	2019-08-21	16.228 mi
Registration #16	2020-08-11	16.513 mi
Registration #17	2020-08-11	16.798 mi

[More info >](#)



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	37 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	B3516201