





report date: 2024-03-28

## General information

Make	VOLKSWAGEN
Model	CC MATCH TDI BLUEMOTION TECHNOLOGY
Colour	Blue
Year of manufacture	2015
Top speed	123 mph
0 - 100 km/h	9.8 seconds
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	110 kW / 150 HP / 148 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	56.5 mpg
CO2 emission	130 g/km
CO2 label	D



CarCheck.co.uk page 1/11



report date: 2024-03-28

## Internet history

#### Entry 1

Date 2022-05-26

Pictures 36

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



KR65BFZ report date: 2024-03-28

MOT history

MOT expiry date	2024-05-15
MOT pass rate	100 %
MOT passed	6
Failed MOT tests	0
Total advice items	11
Total items failed	0

MOT #6		2023-05-15 10:28
MOT test	number	835484538523
Result		✓ Passed
Next expiry date 2024-05-1		2024-05-15
Advice	Offside Front Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Inner Tyre slightly damaged/cracking or perishing and inner w	all (5.2.3 (d) (ii))

MOT #5	202	22-05-16 06:35
MOT test	number	341854994206
Result		✓ Passed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	(a) (ii))
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 ( $lpha$	a) (ii))
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number

Result

Advice

Offside Front Tyre worn close to legal limit/worn on edge 235/40ZR 18 (5.2.3 (e))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3	2020-11-23 14:38
MOT test number	731921930076
Result	✓ Passed
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #2	2019-11-09 14:55
MOT test number	432358138438
Result	✓ Passed
MOT #1	2018-11-02 16:07
MOT test number	771584104847
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

# Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	15 May 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 5/11




report date: 2024-03-28

### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



#### Extra VOLKSWAGEN salvage check



**Category** 

**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



KR65BFZ report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Do here.	
*********	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
***************************************	
********	
***************************************	
************	
Plate changes	More info >
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK SAIN
Plate since	
Current registration	UK ZIS
Plate since	
	More info >

CarCheck.co.uk page 8/11



KR65BFZ report date: 2024-03-28

#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2015-11-25
Last registration	2023-05-15
Complete history	See info



Registration #1	2015-11-25	22 mi
Registration #2	2018-11-02	11.567 mi
Registration #3	2019-11-09	14.244 mi
Registration #4	2020-11-23	17.849 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

page 10/11 CarCheck.co.uk



report date: 2024-03-28

## Car features

50225	Air conditionir
50295	
60482	
60501	
60566	
0567	
60569	

# Safety ratings

NCAP rating	****
Adult	87%
Children	79%
Pedestrian	48%
Safety systems	71%
Overall rating	76%
Video	see crash video



# Dimensions & weight

Width	2041 mm
Height	1703 mm
Length	4426 mm
Wheel base	2604 mm
Kerb weight	1597 kg
Max. allowed weight	2150 kg

# Additional information

Fuel tank capacity	64 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack co.uk	page 11/11

CarCheck.co.uk page 11/11

Number of seats	5
Number of axles	2
Engine number	CUVC429980