





report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 PURETECH DSTYLE PLUS S/S
Colour	Purple
Year of manufacture	2015
Top speed	118 mph
0 - 60 mph	9.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	205 Nm at 1.500 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.9 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	104 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 3

Date 2023-03-18

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date 2022-12-01

Pictures 18

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-05-26

Pictures 52

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-04-11
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	17
Total items failed	3

	2024-04-12 14:39
number	202455863568
	✓ Passed
ry date	2025-04-11
Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Offside Front Service brake binding but not excessively (1.2.1 (f))	
Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Offside Front Service brake binding but not excessively (1.2.1 (f)) Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #8	2024-04-12 13:14
MOT test number	449863474621
Result	× Failed
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Offside Front Service brake binding but not excessively (1.2.1 (f))	
Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
Minor (b) (i)) Nearside Registration plate lamp inoperative in the case of multiple lamps or lamps or lamps (b) (ii))	light sources (4.7.1
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #7 2022-11-01 16:57

MOT test number 293459713348

Result
✓ Passed

MOT #6 2022-04-02 13:49

MOT test number 458481064657

Advice Oil leak, but not excessive Engine. (8.4.1 (a) (i))

MOT #5 2022-04-02 13:11

MOT test number 633684996567

Result X Failed

Fail Nearside Rear Inner Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Oil leak, but not excessive Engine. (8.4.1 (a) (i))

MOT #4 2021-02-16 15:57

MOT test number 549146597732

Result ✓ Passed

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Rear Exhaust mounting defective Welds broken (6.1.2 (a))

MOT #3 2020-02-17 11:40

MOT test number 347114380171

Result
✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Tyres perished

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre perished

CarCheck.co.uk page 4/12



MOT #2

MOT test number

292239447585

Result

✓ Passed

MOT #1

2018-02-18 10:43

MOT #1	2018-02-18 10:43
MOT test number	275801639001
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	11 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

PE15UHK

report date: 2024-03-29

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report here.

More info >

Plate changes

about of pliates

furthe scinors

See in this check if this CITROEN had different number plates.

以K UK

AIN UK

More info >

CarCheck.co.uk page 9/12



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-03-26
Last registration	2024-04-12
Complete history	See info



Registration #1	2015-03-26	27 mi
Registration #2	2018-02-18	5.533 mi
Registration #3	2019-02-08	13.050 mi
Registration #4	2020-02-17	20.645 mi
Registration #5	2021-02-16	26.916 mi
Registration #6		11.777 es
Registration #7	2022-04-02	40.244 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 mg

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1708 mm
Height	1460 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1070 kg
Max. allowed weight	1578 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	XV120080873

CarCheck.co.uk page 12/12