





report date: 2024-03-28

General information

| Make | MAZDA |
|---------------------|---------------------|
| Model | 3 D VENTURE EDITION |
| Colour | Silver |
| Year of manufacture | 2013 |
| Top speed | 116 mph |
| 0 - 60 mph | 11.0 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 113 BHP |
|-------------------------|---------------------|
| Max. torque | 270 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 5.3 mpg |
| Consumption extra urban | 3.8 mpg |
| Consumption combined | 4.3 mpg |
| CO2 emission | 115 g/km |
| CO2 label | С |



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-11

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

| MOT expiry date | 2024-09-03 |
|--------------------|------------|
| MOT pass rate | 90 % |
| MOT passed | 9 |
| Failed MOT tests | 1 |
| Total advice items | 21 |
| Total items failed | 1 |

| MOT #10 | | 2023-09-04 14:31 |
|-----------|--|------------------|
| MOT test | number | 447180529345 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-09-03 |
| Advice | Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) | |
| Advice | Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) | |
| Advice | Nearside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e)) | |

| MOT #9 | | 2022-03-29 13:21 |
|----------|--|------------------|
| MOT test | number | 966460508165 |
| Result | | ✓ Passed |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Offside Front Shock absorbers has light misting of oil (5.3.2 (b)) | |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Nearside Front Shock absorbers has light misting of oil (5.3.2 (b)) | |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened x2 (1.1.14 | (a) (ii)) |

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #8 2022-03-29 13:21 **MOT** test number 359237106837 Result × Failed **Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b)) Advice Front Brake disc worn, pitted or scored, but not seriously weakened x2 (1.1.14 (a) (ii)) Pass with rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii)) Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b)) **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

 MOT #7
 2021-03-26 09:31

 MOT test number
 595553599746

 Result
 ✓ Passed

 MOT #6
 2021-03-22 09:06

 MOT test number
 312224972220

 Result
 ✓ Passed

MOT #5

MOT test number

Result

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened Both. (1.1.14 (a) (ii))

Advice

(5.2.3 (e))

Passed

Front Tyre worn close to legal limit/worn on edge Both front tyres starting to wear on inner edge.

CarCheck.co.uk page 4/12



SP63VXD

report date: 2024-03-28

MOT #4 2019-03-21 10:11 912675392068 **MOT** test number Result ✓ Passed **Advice** Offside Front Tyre worn close to legal limit/worn on edge Wearing bald on inner edge on 2-1.6mm (5.2.3 (e)) Nearside Front Tyre worn close to legal limit/worn on edge Wearing on edges on 2mm. (5.2.3 (e)) **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both. (1.1.14 (a) (ii)) **Advice**

MOT #3 2018-03-07 08:59 701868495488 **MOT** test number Result ✓ Passed **Advice** Under trays fitted **Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) **Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

| MOT #2 | 2017-03-22 18:30 |
|-----------------|------------------|
| MOT test number | 157899402953 |
| Result | ✓ Passed |

| MOT #1 | 2016-09-21 14:16 |
|-----------------|------------------|
| MOT test number | 223578926051 |
| Result | ✓ Passed |

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check





Expires: 3 September 2024

| Tax status | Valid until 1 September |
|------------------|-------------------------|
| Days left | 125 |
| MOT expiry date | 3 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vahiala alaas | 40 |
|---|----------------|
| Vehicle class | 49 |
| Band | С |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

| For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively. | |
|---|-------------|
| | |
| | |
| | |
| | |
| ******** | |
| | |
| *************************************** | |
| | |
| | More info > |
| | |
| Plate changes | |
| See in this check if this MAZDA had different number plates. | |
| Number of plates | , |
| Current registration | UK NE |
| Plate since | |
| Current registration | UK ZIS |
| Plate since | |
| | |
| | More info > |

CarCheck.co.uk page 9/12



SP63VXI

report date: 2024-03-28

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 12 |
| First mileage registration | 2013-10-07 |
| Last registration | 2023-09-04 |
| Complete history | See info |



| Registration #1 | 2013-10-07 | 28 mi |
|------------------|------------|-----------|
| Registration #2 | 2016-09-21 | 42.925 mi |
| Registration #3 | 2017-03-22 | 47.237 mi |
| Registration #4 | 2018-03-07 | 51.667 mi |
| Registration #5 | 2019-03-21 | 55.841 mi |
| Registration #6 | 2020-03-11 | 59.811 mi |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | 10.777 es |

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 86% |
| Children | 84% |
| Pedestrian | 51% |
| Safety systems | 71% |
| Overall rating | 77% |
| Video | see crash video |



Dimensions & weight

| Width | 1755 mm |
|---------------------|---------|
| Height | 1470 mm |
| Length | 4460 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1309 kg |
| Max. allowed weight | 1830 kg |

Additional information

| Fuel tank capacity | 55 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | Y6 357067 |

CarCheck.co.uk page 12/12