



report date: 2024-03-28

General information

| | |
|---------------------|--------------------|
| Make | VOLVO |
| Model | XC90 D5 ACTIVE AWD |
| Colour | Black |
| Year of manufacture | 2010 |
| Top speed | 118 mph |
| 0 - 60 mph | 11.1 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 182 BHP |
| Max. torque | 400 Nm at 2.750 rpm |
| Engine capacity | 2.400 cc |
| Cylinders | 5 |
| Fuel type | Diesel |
| Consumption city | 25.4 mpg |
| Consumption extra urban | 40.4 mpg |
| Consumption combined | 33.2 mpg |
| CO2 emission | 224 g/km |
| CO2 label | K |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-02-06 |
| Pictures | 1 |
| Listing price | View report |



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2023-08-08 |
| MOT pass rate | 69 % |
| MOT passed | 9 |
| Failed MOT tests | 4 |
| Total advice items | 12 |
| Total items failed | 7 |

| | |
|------------------|---|
| MOT #13 | 2022-08-09 13:24 |
| MOT test number | 596614600142 |
| Result | ✓ Passed |
| Next expiry date | 2023-08-08 |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|-----------------|------------------|
| MOT #12 | 2021-07-22 13:46 |
| MOT test number | 786216510392 |
| Result | ✓ Passed |

| | |
|-----------------|---|
| MOT #11 | 2021-07-14 15:37 |
| MOT test number | 399469815262 |
| Result | ✗ Failed |
| Fail | Nearside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i)) |

| | |
|-----------------|------------------|
| MOT #10 | 2019-08-06 09:18 |
| MOT test number | 577702895682 |
| Result | ✓ Passed |

**MOT #9** 2018-07-25 17:09**MOT test number** 928148590848**Result** ✓ Passed**MOT #8** 2018-07-24 15:44**MOT test number** 826844955719**Result** ✗ Failed**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a))**MOT #7** 2017-07-10 11:43**MOT test number** 780856071488**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Rear Seat belt cut but webbing not significantly weakened (5.2.2a)**MOT #6** 2016-06-30 15:09**MOT test number** 556712095307**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Front Side repeater has a product on the lens but not adversely affecting light output (1.4.A.2e)**MOT #5** 2015-09-04 11:29**MOT test number** 269466110418**Result** ✓ Passed

**MOT #4** 2015-09-04 09:25**MOT test number** 833931984611**Result** ✗ Failed**Fail** Nearside Front Side repeater not working (1.4.A.2c)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #3** 2014-09-10 14:48**MOT test number** 319553054238**Result** ✓ Passed**Advice** Offside Rear Seat belt damaged but webbing not significantly weakened (5.2.2a)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Notice** Emission not detected**MOT #2** 2014-09-10 09:39**MOT test number** 376853454216**Result** ✗ Failed**Fail** Nearside Front Side repeater not working (1.4.A.2c)**Notice** Emission not detected**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Rear Seat belt damaged but webbing not significantly weakened (5.2.2a)**MOT #1** 2013-09-18 09:01**MOT test number** 649731263272**Result** ✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-28 |
| Current registration | |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 15 |
| First mileage registration | 2010-09-03 |
| Last registration | 2022-08-09 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2010-09-03 | 8 mi |
| Registration #2 | 2013-09-18 | 40.369 mi |
| Registration #3 | 2014-09-10 | 51.644 mi |
| Registration #4 | 2014-09-10 | 51.644 mi |
| Registration #5 | 2015-09-04 | 63.041 mi |
| Registration #6 | 2015-09-04 | 63.045 mi |
| Registration #7 | 2016-06-30 | 69.989 mi |
| Registration #8 | 2017-07-10 | 81.209 mi |
| Registration #9 | 2018-06-20 | 92.377 mi |
| Registration #10 | 2019-06-20 | 103.545 mi |
| Registration #11 | 2020-06-20 | 114.713 mi |
| Registration #12 | 2021-06-20 | 125.881 mi |
| Registration #13 | 2022-06-20 | 137.049 mi |
| Registration #14 | 2023-06-20 | 148.217 mi |
| Registration #15 | 2024-06-20 | 159.385 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1898 mm |
| Height | 1784 mm |
| Length | 4798 mm |
| Wheel base | 2857 mm |
| Kerb weight | 2130 kg |
| Max. allowed weight | 2750 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 68 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 7 |

Engine number

784551