



RENAULT



report date: 2024-03-28

General information

| | |
|---------------------|----------------------|
| Make | RENAULT |
| Model | ZOE DYNAMIQUE INTENS |
| Colour | White |
| Year of manufacture | 2015 |
| Top speed | 84 mph |
| 0 - 60 mph | 13.5 seconds |
| Gearbox | 1 speed automatic |

Engine & fuel consumption

| | |
|-------------|---------------------|
| Power | 87 BHP |
| Max. torque | 220 Nm at 2.500 rpm |
| Fuel type | Electricity |




LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-13 |
| Pictures | 21 |
| Listing price | View report |



source: yesauto.com



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-06-21 |
| MOT pass rate | 86 % |
| MOT passed | 6 |
| Failed MOT tests | 1 |
| Total advice items | 16 |
| Total items failed | 4 |

MOT #7 2023-06-06 14:21

MOT test number 888712455428

Result ✓ Passed

Next expiry date 2024-06-21

Advice Front Tyre worn close to legal limit/worn on edge both sides of vehicle (5.2.3 (e))**Advice** Front Shock absorbers has slight external damage to the casing both sides of vehicle slightly corroded (5.3.2 (b))

MOT #6 2022-06-22 11:15

MOT test number 464597992186

Result ✓ Passed**Advice** Front shock absorbers corroded

MOT #5 2022-06-14 15:31

MOT test number 160319444624

Result ✗ Failed**Advice** Front shock absorbers corroded**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt upper link balljoint (5.3.4 (b) (ii))

**MOT #4** 2021-06-21 08:21**MOT test number** 842510432072**Result** ✓ Passed**MOT #3** 2020-09-01 09:33**MOT test number** 633480175650**Result** ✓ Passed

- Advice** Offside Rear All direction indicators slightly discoloured (4.4.3 (a))
- Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear All direction indicators slightly discoloured (4.4.3 (a))
- Advice** Osr fog light broken
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #2 2019-08-30 15:25**MOT test number** 219319952249**Result** ✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking in tread area (5.2.3 (d) (ii))
- Advice** Offside Rear Nail in tyre punctured in tread area
- Advice** Offside Front Tyre slightly damaged/cracking or perishing cracking on outer tread area (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracking in tread area (5.2.3 (d) (ii))

MOT #1 2018-09-18 13:20**MOT test number** 572074087053**Result** ✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
21 June 2024

| | |
|-------------------|--------------------|
| Tax status | Valid until 1 June |
|-------------------|--------------------|

| | |
|------------------|----|
| Days left | 34 |
|------------------|----|

| | |
|------------------------|--------------|
| MOT expiry date | 21 June 2024 |
|------------------------|--------------|

| | |
|-------------------------|---------------------------------|
| Full MOT history | See MOT history |
|-------------------------|---------------------------------|



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this RENAULT had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2019-09-29 |
| Current registration | ***** |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

| | | |
|-------------------|---------|------|
| Finance company | RENAULT | 2024 |
| Date of agreement | RENAULT | 2024 |
| Agreement type | RENAULT | 2024 |
| Agreement term | RENAULT | 2024 |
| Agreement number | RENAULT | 2024 |
| Contact info | RENAULT | 2024 |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 9 |
| First mileage registration | 2015-09-30 |
| Last registration | 2023-06-06 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2015-09-30 | 15 mi |
| Registration #2 | 2018-09-18 | 17.437 mi |
| Registration #3 | 2019-08-30 | 20.410 mi |
| Registration #4 | 2020-09-01 | 24.536 mi |
| Registration #5 | 2021-06-01 | 25.277 mi |
| Registration #6 | 2022-06-01 | 25.277 mi |
| Registration #7 | 2022-06-01 | 25.277 mi |
| Registration #8 | 2022-06-01 | 25.277 mi |
| Registration #9 | 2023-06-06 | 25.277 mi |

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 89% |
| Children | 80% |
| Pedestrian | 66% |
| Safety systems | 85% |
| Overall rating | 82% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1730 mm |
| Height | 1562 mm |
| Length | 4084 mm |
| Wheel base | 2588 mm |
| Kerb weight | 1468 kg |
| Max. allowed weight | 1943 kg |

Additional information

| | |
|-----------------|----------------|
| Fuel delivery | Not Applicable |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |

| | |
|---------------|---------|
| Engine number | A060991 |
|---------------|---------|