



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX35 CRDI STYLE
Colour	Silver
Year of manufacture	2010
Top speed	112 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.500 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-01-31
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date 2024-02-24**MOT pass rate** 65 %**MOT passed** 11**Failed MOT tests** 6**Total advice items** 32**Total items failed** 11**MOT #17** 2023-02-22 12:05**MOT test number** 963088372062**Result** Passed**Next expiry date** 2024-02-24**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #16** 2023-02-22 12:05**MOT test number** 429454906045**Result** Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Pass with rectification** Prop shaft flexible coupling excessively deteriorated (6.1.7 (d) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Pass with rectification** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**MOT #15** 2022-02-25 14:44**MOT test number** 328981579073**Result** ✓ Passed**MOT #14** 2020-12-10 10:40**MOT test number** 915499908097**Result** ✓ Passed**MOT #13** 2020-11-23 16:13**MOT test number** 479676947760**Result** ✗ Failed**Advice** Offside Rear Inner Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))**Fail** Offside Front Outer Side repeater not working (4.4.1 (a) (ii))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Inner Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #12** 2019-11-22 14:44**MOT test number** 624889579479**Result** ✓ Passed**MOT #11** 2019-11-21 12:46**MOT test number** 712377518414**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar corroded and seriously weakened (5.3.3 (b) (i))**Fail** Offside Front Anti-roll bar damaged and seriously weakened (5.3.3 (b) (i))

**MOT #10** 2019-02-16 12:28**MOT test number** 332879290948**Result** ✓ Passed**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge and slight misshape (5.2.3 (e))**Advice** Chip screen**Advice** Nearside Rear tyre slight misshape**MOT #9** 2018-06-21 15:51**MOT test number** 114324324372**Result** ✓ Passed**MOT #8** 2017-07-25 15:56**MOT test number** 279689995545**Result** ✓ Passed**Advice** Offside side repeater lens cracked**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside rear tyre wearing on inner edge of tread**Advice** Boot full**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Rear heat shield insecure**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front discs worn

**MOT #7** 2017-07-24 13:45**MOT test number** 976024104571**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside side repeater lens cracked
- Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Advice** Nearside rear tyre wearing on inner edge of tread
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Boot full
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Rear heat shield insecure
- Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Front discs worn

MOT #6 2016-07-21 11:02**MOT test number** 194556205162**Result** ✓ Passed

- Advice** Front Tyre worn close to the legal limit both (4.1.E.1)

MOT #5 2015-08-07 10:31**MOT test number** 319229715449**Result** ✓ Passed**MOT #4** 2015-07-28 14:17**MOT test number** 707879705226**Result** ✗ Failed

- Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)



MOT #3	2014-07-30 16:39
MOT test number	309221714269
Result	✓ Passed

MOT #2	2014-07-29 15:09
MOT test number	248790114279
Result	✗ Failed
Fail	Nearside Front coil spring broken (2.4.C.1a)
Fail	Front Brakes imbalanced across an axle (3.7.B.5b)

MOT #1	2013-07-26 14:36
MOT test number	395307703210
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
22 November 2023

X

MOT

Expired:
24 February 2024

Tax status	Expired at 22 November 2023
Days left	160 days too late
MOT expiry date	24 February 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-07-30
Last registration	2023-02-22
Complete history	See info



Registration #1	2010-07-30	21 mi
Registration #2	2013-07-26	15.289 mi
Registration #3	2014-07-29	21.686 mi
Registration #4	2014-07-30	21.688 mi
Registration #5	2015-07-28	28.203 mi
Registration #6	2015-08-07	28.210 mi
Registration #7	2016-07-21	40.012 mi
Registration #8	2017-07-24	66.452 mi
Registration #9	2017-07-25	66.453 mi
Registration #10	2018-06-21	89.348 mi
Registration #11	2019-06-21	115.348 mi
Registration #12	2019-06-21	115.348 mi
Registration #13	2019-06-21	115.348 mi
Registration #14	2019-06-21	115.348 mi
Registration #15	2019-06-21	115.348 mi
Registration #16	2019-06-21	115.348 mi
Registration #17	2019-06-21	115.348 mi
Registration #18	2019-06-21	115.348 mi
Registration #19	2019-06-21	115.348 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1660 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1679 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4HAAU241874