





report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	GLE GLE 250 D 4MATIC AMG NIGHT EDI
Colour	Black
Year of manufacture	2018
Top speed	130 mph
0 - 60 mph	8.6 seconds
Gearbox	9 speed automatic

Engine & fuel consumption

Power	150 kW / 204 HP / 201 BHP
Max. torque	500 Nm at 1.800 rpm
Engine capacity	2.143 сс
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G



CarCheck.co.uk page 1/11



BC18XTS
report date: 2024-03-28

Internet history

Entry 2

Date	2021-10-13	
Pictures	1	
Listing price	<u>View report</u>	



source: cargurus.co.uk

Entry 1

Date	2021-10-12
Pictures	0
Listing price	View report

source: heycar.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

MOT expiry date	2024-08-24
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	10
Total items failed	1

MOT #4	2023-08-25 13:44
MOT test number	384829588467
Result	✓ Passed
Next expiry date	2024-08-24
Minor Offside Side repeater lens defective which has no effect on emitted light (4.4.3)	1 (b) (i))
Advice Offside Rear Nail in tyre	
Advice Central Front Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #3	2022-08-01 11:06
MOT test number	483647274698
Result	✓ Passed

MOT #2		2021-07-10 10:36
MOT test	number	918597100046
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #1 2021-07-09 11:50

MOT test number 566929038215

Result X Failed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 November
Days left	187
MOT expiry date	24 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
First licence fee (12 months)	£ 645,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 1.040,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



BC18XTS
report date: 2024-03-28

Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date

Category


Damage 2

Category

Type

Date

Туре



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



BC18XTS
report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

More info >

Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How may MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. It report here.	

	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	OK OK
Plate since	

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-07-31
Last registration	2023-08-25
Complete history	See info



Registration #1	2018-07-31	9 mi
Registration #2	2021-07-09	13.175 mi
Registration #3	2021-07-10	13.197 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.177 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

60225	Air conditionin
60295	
0482	
0501	
0566	
0567	
0569	
iew the complete MERCEDES-BENZ factory list for this	More info >

Dimensions & weight

Width	2141 mm
Height	1789 mm
Length	4819 mm
Wheel base	2915 mm
Kerb weight	2065 kg

Additional information

Fuel tank capacity	93 I
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	65196034652893

CarCheck.co.uk page 11/11