



report date: 2024-03-29

General information

Make	MAZDA
Model	MX-5 I
Colour	Black
Year of manufacture	2006
Top speed	130 mph
0 - 60 mph	7.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	166 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	183 g/km
CO2 label	I






Internet history

Entry 8

Date	2021-11-03
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)

Entry 7

Date	2021-10-05
Pictures	15
Listing price	View report



source: [autotrader.co.uk](#)

Entry 6

Date	2021-09-19
Pictures	15
Listing price	View report



source: [autotrader.co.uk](#)

Entry 5

Date	2021-09-04
------	------------


Pictures	15
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 4


Date	2021-08-06
Pictures	15
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 3

Date	2021-07-06
Pictures	15
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 2

Date	2021-06-07
Pictures	15
Listing price	View report



source: autotrader.co.uk

Entry 1

Date	2021-05-23
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2022-11-18
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	27
Total items failed	5

MOT #18 2021-11-19 19:06

MOT test number 221773894115

Result ✓ Passed

Next expiry date 2022-11-18

Advice Lower Integral body structure is deformed but structural rigidity is not significantly reduced (6.1.1 (a) (i))

Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

MOT #17 2020-05-14 10:42

MOT test number 553548488772

Result ✓ Passed

Advice Nearside Front shock absorber corroded

Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive sill/floor corroded/ small hole (5.3.6 (a) (i))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #16** 2020-05-12 11:33**MOT test number** 601415106611**Result** ✗ Failed**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive sill/floor corroded/ small hole (5.3.6 (a) (i))**Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Nearside Front shock absorber corroded**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #15** 2019-05-28 12:15**MOT test number** 306885726146**Result** ✓ Passed**MOT #14** 2018-03-20 10:19**MOT test number** 374709321019**Result** ✓ Passed**Advice** Both rear tyre perished no cords exposed time test**MOT #13** 2017-04-20 13:50**MOT test number** 700485934721**Result** ✓ Passed

**MOT #12** 2016-04-19 14:23**MOT test number** 257548817506**Result** ✓ Passed

- Advice** Nearside Rear slight corrosion at chassis leg
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Rear slight corrosion at chassis leg

MOT #11 2016-04-12 13:15**MOT test number** 138323792899**Result** ✗ Failed

- Advice** Offside Rear nail in tyre
- Advice** Nearside Rear slight corrosion at chassis leg
- Advice** Offside Rear slight corrosion at chassis leg
- Fail** Offside Front coil spring broken (2.4.C.1a)

MOT #10 2015-04-14 17:10**MOT test number** 279174305170**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components

MOT #9 2015-04-14 12:00**MOT test number** 355564805106**Result** ✗ Failed

- Fail** Offside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Nail in offside rear tyre

**MOT #8** 2014-04-15 16:38**MOT test number** 195335204154**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar linkage worn but not seriously weakened (2.4.G.1)**Advice** Offside Rear Anti-roll bar linkage worn but not seriously weakened (2.4.G.1)**MOT #7** 2014-04-15 11:51**MOT test number** 238725104196**Result** ✗ Failed**Advice** Nearside Rear Anti-roll bar linkage worn but not seriously weakened (2.4.G.1)**Fail** Nearside Front Anti-roll bar linkage insecure (2.4.G.1)**Advice** Offside Rear Anti-roll bar linkage worn but not seriously weakened (2.4.G.1)**MOT #6** 2013-04-24 19:49**MOT test number** 236414213185**Result** ✓ Passed**MOT #5** 2012-07-26 11:56**MOT test number** 397078002433**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in nearside rear tyre**MOT #4** 2011-07-27 14:50**MOT test number** 315138201435**Result** ✓ Passed



MOT #3	2011-07-27 10:07
MOT test number	886398601209
Result	✗ Failed
<div><div>Fail</div>Nearside Rear Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)</div>	

MOT #2	2010-07-26 11:07
MOT test number	303647100442
Result	✓ Passed

MOT #1	2009-07-29 09:48
MOT test number	200070119240
Result	✓ Passed



Tax & MOT check

×

Untaxed

Tax expired:
1 November 2022

×

MOT

Expired:
18 November 2022

Tax status

Expired at 1 November 2022

Days left

546 days too late

MOT expiry date

18 November 2022

Full MOT history

[See MOT history](#)

Tax calculation


Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2006-07-26
Last registration	2021-11-19
Complete history	See info



Registration #1	2006-07-26	17 mi
Registration #2	2009-07-29	11.753 mi
Registration #3	2010-07-26	21.666 mi
Registration #4	2011-07-27	29.938 mi
Registration #5	2011-07-27	29.938 mi
Registration #6	2012-07-26	39.682 mi
Registration #7	2013-04-24	41.586 mi
Registration #8	2014-04-15	44.872 mi
Registration #9	2014-04-15	44.872 mi
Registration #10	2015-04-14	48.084 mi
Registration #11	2015-04-14	48.084 mi
Registration #12	2016-04-12	50.984 mi
Registration #13	2016-04-19	51.044 mi
Registration #14	2017-04-20	52.068 mi
Registration #15	2018-05-01	53.117 mi
Registration #16	2018-05-01	53.117 mi
Registration #17	2018-05-01	53.117 mi
Registration #18	2018-05-01	53.117 mi
Registration #19	2018-05-01	53.117 mi
Registration #20	2018-05-01	53.117 mi
Registration #21	2018-05-01	53.117 mi
Registration #22	2018-05-01	53.117 mi
Registration #23	2018-05-01	53.117 mi
Registration #24	2018-05-01	53.117 mi
Registration #25	2018-05-01	53.117 mi
Registration #26	2018-05-01	53.117 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1720 mm
Height	1245 mm
Length	3995 mm
Wheel base	2330 mm
Kerb weight	1080 kg
Max. allowed weight	1355 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	LF705002