




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	EOS GTI EDITION30 T 230
Colour	Black
Year of manufacture	2007
Top speed	150 mph
0 - 60 mph	6.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	227 BHP
Max. torque	300 Nm at 2.200 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.4 mpg
CO2 emission	194 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-12-23
Pictures	17
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2022-06-16
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	34
Total items failed	6

MOT #15 2021-05-20 16:41

MOT test number 174757689138

Result ✓ Passed

Next expiry date 2022-06-16

Minor Windscreen damaged but not adversely affecting driver's view In Zone B (3.2 (a) (i))

Advice Offside Steering Arm Has relative Play Within its Steering inner Joint

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice TPMS light on Indicating a Tyre low Pressure

MOT #14 2021-05-20 10:39

MOT test number 335420010446

Result ✗ Failed

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Steering Arm Has relative Play Within its Steering inner Joint

Fail Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice TPMS light on Indicating a Tyre low Pressure

Minor Windscreen damaged but not adversely affecting driver's view In Zone B (3.2 (a) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #13**

2020-06-17 10:25

MOT test number

889826655252

Result

✓ Passed

- Advice** Nearside Front drop link gaiter small split
- Advice** Nearside Front brake discs inner edge corroded
- Advice** Nearside Front steering rack inner joint slight play
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Windscreen chipped and cracked in zone b

MOT #12

2019-06-04 16:29

MOT test number

934161959281

Result

✓ Passed

- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #11**

2019-05-20 14:56

MOT test number

812403466891

Result**✗ Failed**

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Fail Front Windscreen washer not working (3.5 (a))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Brake pad warning lamp illuminated

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10

2018-02-10 16:51

MOT test number

129749862057

Result**✓ Passed**

Advice Nearside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2017-02-18 13:57**MOT test number** 857516329565**Result** ✓ Passed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2016-02-16 16:44**MOT test number** 561612318803**Result** ✓ Passed**MOT #7** 2015-02-20 16:13**MOT test number** 208041555071**Result** ✓ Passed**MOT #6** 2014-03-18 16:18**MOT test number** 419807174034**Result** ✓ Passed**MOT #5** 2013-03-04 16:10**MOT test number** 359973363004**Result** ✓ Passed**MOT #4** 2012-03-19 17:30**MOT test number** 419519572021**Result** ✓ Passed**MOT #3** 2011-03-28 17:18**MOT test number** 756007981063**Result** ✓ Passed



MOT #2	2010-03-29 12:33
MOT test number	392498380079
Result	✓ Passed

MOT #1	2010-03-29 10:47
MOT test number	173568880057
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✕
Untaxed

Tax expired:
31 January 2022

✕
MOT

Expired:
16 June 2022

Tax status	Expired at 31 January 2022
Days left	820 days too late
MOT expiry date	16 June 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	EX07UGL
Plate since	2019-06-29
Current registration	EX07UGL
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-03-27
Last registration	2021-05-20
Complete history	See info



Registration #1	2007-03-27	12 mi
Registration #2	2010-03-29	13.153 mi
Registration #3	2010-03-29	13.153 mi
Registration #4	2011-03-28	19.059 mi
Registration #5	2012-03-19	24.711 mi
Registration #6	2013-03-04	31.288 mi
Registration #7	2014-03-18	41.575 mi
Registration #8	2015-02-20	49.815 mi
Registration #9	2016-02-16	59.614 mi
Registration #10	2016-05-20	65.377 mi
Registration #11	2016-05-20	65.377 mi
Registration #12	2016-05-20	65.377 mi
Registration #13	2016-05-20	65.377 mi
Registration #14	2016-05-20	65.377 mi
Registration #15	2016-05-20	65.377 mi
Registration #16	2016-05-20	65.377 mi
Registration #17	2016-05-20	65.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1469 mm
Length	4216 mm
Wheel base	2578 mm
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

NOT KNOWN