



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT TDI SE
Colour	Silver
Year of manufacture	-
Top speed	127 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg



**MOT history****MOT #14**

2020-11-20 17:22

MOT test number

746150542507

Result

✓ Passed

Next expiry date

2021-11-22

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Coil spring corroded both rear (5.3.1 (b) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Lower Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Lower Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))

**MOT #13**

2020-11-20 09:52

MOT test number

651421449679

Result**✗ Failed**

Advice Offside Rear Lower Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MAJOR Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

MAJOR Nearside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

MAJOR Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

MAJOR Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Nearside Rear Lower Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MAJOR Undertray insecure (8.1.1 (b) (i))

Minor Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MAJOR Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MAJOR Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MAJOR Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Coil spring corroded both rear (5.3.1 (b) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #12**

2019-11-23 11:10

MOT test number

146805899918

Result

✓ Passed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #11

2018-08-31 12:38

MOT test number

344573041443

Result

✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #10

2018-08-30 15:18

MOT test number

829604324536

Result

✗ Failed

MAJOR Brake pad(s) wear indicator illuminated (1.1.13 (a) (i))

MAJOR Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MAJOR Offside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #9

2017-08-05 11:28

MOT test number

503398516167

Result

CarCheck.co.uk

✓ Passed
page 4/12

**MOT #8** 2016-08-06 10:25**MOT test number** 387480488396**Result** ✓ Passed**MOT #7** 2015-08-13 18:46**MOT test number** 657505625243**Result** ✓ Passed**MOT #6** 2015-08-13 17:35**MOT test number** 555545425226**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2014-12-01 12:15**MOT test number** 407495834318**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2013-11-29 10:32**MOT test number** 455873233457**Result** ✓ Passed**MOT #3** 2012-11-28 14:31**MOT test number** 596503832317**Result** ✓ Passed



MOT #2	2011-11-29 15:34
MOT test number	256293331343
Result	✓ Passed
MOT #1	2010-10-08 11:56
MOT test number	393241980461
Result	✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	YD57XCU
Plate since	2019-03-29
Current registration	YD57XCU
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2007-10-15
Last registration	2020-11-20
Complete history	See info



Registration #1	2007-10-15	24 mi
Registration #2	2010-10-08	60.137 mi
Registration #3	2011-11-29	85.320 mi
Registration #4	2012-11-28	93.131 mi
Registration #5	2013-11-29	100.232 mi
Registration #6	2014-12-01	108.069 mi
Registration #7	2015-08-13	114.236 mi
Registration #8	2015-08-13	114.238 mi
Registration #9	2016-08-13	114.238 mi
Registration #10	2016-08-13	114.238 mi
Registration #11	2016-08-13	114.238 mi
Registration #12	2016-08-13	114.238 mi
Registration #13	2016-08-13	114.238 mi
Registration #14	2016-08-13	114.238 mi
Registration #15	2016-08-13	114.238 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1517 mm
Length	4774 mm
Wheel base	2709 mm
Kerb weight	1715 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BKP 137175