



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT TDI SE
Colour	Silver
Year of manufacture	2006
Top speed	114 mph
0 - 60 mph	12.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	157 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-05
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-20
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	55
Total items failed	4

MOT #21	2023-07-21 16:02
MOT test number	263921818802
Result	✓ Passed
Next expiry date	2024-07-20

MOT #20	2022-07-15 13:34
MOT test number	432953686200
Result	✓ Passed
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear most bush (5.3.4 (a) (i))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear most bush (5.3.4 (a) (i))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #19**

2022-07-14 12:37

MOT test number

993557673563

Result**✗ Failed**

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear most bush (5.3.4 (a) (i))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MAJOR Brake pressure/vacuum build up too slow (1.1.3 (b))

MAJOR Offside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear most bush (5.3.4 (a) (i))

MAJOR Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

MAJOR Braking system leaking Brake servo pipe (1.1.3 (d))

MOT #18

2021-06-02 14:59

MOT test number

486228544438

Result**✓ Passed**

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17

2021-05-14 16:29

MOT test number

664994388940

Result**✗ Failed**

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MAJOR Offside Front Suspension arm pin or bush excessively worn front (5.3.4 (a) (i))

MAJOR Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Nearside Front Suspension arm pin or bush excessively worn front (5.3.4 (a) (i))

**MOT #16** 2020-06-30 14:05**MOT test number** 116262405052**Result** ✓ Passed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Rear Inner Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Front Inner Tyre worn close to legal limit/worn on edge NSF and OSF (5.2.3 (e))**MOT #15** 2020-06-22 12:57**MOT test number** 623336775598**Result** ✗ Failed**MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))**MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Rear Inner Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MAJOR** Nearside Front Headlamp lens seriously defective (4.1.1 (b) (ii))**MAJOR** Nearside Front Lower Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Front Inner Tyre worn close to legal limit/worn on edge NSF and OSF (5.2.3 (e))**MAJOR** Offside Front Headlamp lens seriously defective (4.1.1 (b) (ii))

**MOT #14**

2019-06-20 16:19

MOT test number

673934265508

Result

✓ Passed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush split and worn (5.3.4 (a) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #13

2019-06-18 09:22

MOT test number

885168860912

Result

✗ Failed

MAJOR Nearside Front Outer Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush split and worn (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge advice replace (5.2.3 (e))

MAJOR Windscreen washer provides insufficient washer liquid both jets (3.5 (a))

MAJOR Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

DANGEROUS Offside Front Tyre has ply or cords exposed worn inner tread exposing cords (5.2.3 (d) (ii))

MAJOR Electronic parking brake warning indicates a malfunction (1.1.6 (e))

MOT #12

2018-06-27 14:00

MOT test number

617699663942

Result

✓ Passed

MOT #11

2018-06-27 12:39

MOT test number

907742901946

Result

✗ Failed

MAJOR Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))

**MOT #10** 2017-06-15 15:08**MOT test number** 822997971291**Result** Passed**MOT #9** 2017-06-14 09:33**MOT test number** 374111201064**Result** Failed

Fail Offside Front Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Fail Parking brake: efficiency below requirements (3.7.B.7)

Fail Nearside Front Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Fail Offside Rear rear brake binding (3.7.B.1)

MOT #8 2016-06-28 08:53**MOT test number** 969503444093**Result** Passed

Advice Offside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

Advice Nearside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

MOT #7 2015-06-10 12:12**MOT test number** 719911365112**Result** Passed**MOT #6** 2014-06-18 13:33**MOT test number** 745219664116**Result** Passed**MOT #5** 2013-06-21 12:40**MOT test number** 909522773121**Result** Passed

**MOT #4** 2012-06-12 13:32**MOT test number** 639694762138**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2011-06-15 10:22**MOT test number** 889706661102**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2010-05-14 14:31**MOT test number** 371054930185**Result** ✓ Passed**MOT #1** 2009-05-14 10:44**MOT test number** 611324139183**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
20 July 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	20 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	YP06UYR
Plate since	2019-03-29
Current registration	YP06UYR
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-05-19
Last registration	2023-07-21
Complete history	See info



Registration #1	2006-05-19	12 mi
Registration #2	2009-05-14	43.442 mi
Registration #3	2010-05-14	57.290 mi
Registration #4	2011-06-15	73.989 mi
Registration #5	2012-06-12	86.387 mi
Registration #6	2013-06-21	91.892 mi
Registration #7	2014-06-18	97.307 mi
Registration #8	2015-06-10	105.113 mi
Registration #9	2016-06-28	111.384 mi
Registration #10	2017-06-14	112.567 mi
Registration #11	2017-06-15	112.571 mi
Registration #12	2018-06-27	125.623 mi
Registration #13	2019-06-27	125.623 mi
Registration #14	2019-06-27	125.623 mi
Registration #15	2019-06-27	125.623 mi
Registration #16	2019-06-27	125.623 mi
Registration #17	2019-06-27	125.623 mi
Registration #18	2019-06-27	125.623 mi
Registration #19	2019-06-27	125.623 mi
Registration #20	2019-06-27	125.623 mi
Registration #21	2019-06-27	125.623 mi
Registration #22	2019-06-27	125.623 mi
Registration #23	2019-06-27	125.623 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1517 mm
Length	4774 mm
Wheel base	2709 mm
Kerb weight	1653 kg
Max. allowed weight	2100 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BXE 038893