





report date: 2024-03-29

General information

Make	FORD
Model	MONDEO TITANIUM X 145
Colour	Blue
Year of manufacture	2007
Top speed	130 mph
0 - 60 mph	9.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	144 BHP
Max. torque	190 Nm at 4.500 rpm
Engine capacity	1.999 сс
Cylinders	4
Fuel type	Petrol
Consumption city	25.2 mpg
Consumption extra urban	47.1 mpg
Consumption combined	35.8 mpg
CO2 emission	189 g/km
CO2 label	J



CarCheck.co.uk page 1/13




Internet history

Entry 1

Date	2021-06-16
Pictures	2
Listing price	<u>View report</u>





source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2022-01-11
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	18
Total items failed	6

MOT #14	2021-01-11 13:18
MOT test number	322137305219
Result	✓ Passed
Next expiry date	2022-01-11
Advice Rear Brake pad(s) wearing thin (1.1.1	.3 (a) (ii))
Advice Front Brake pad(s) wearing thin (1.1.	13 (a) (ii))

MOT #13	2020-01-04 09:15
MOT test number	823131830409
Result	✓ Passed
MOT #12	2019-01-12 11:19
MOT test number	801283481908
Result	✓ Passed
Advice Rear tyres worn on inner edges	

MOT #11	2018-01-06 09:3	0
MOT test	number 15424475054	1
Result	✓ Passe	d
Advice	Offside Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)	
Advice	Offsidetrailing arm rubber bush bonding deteriorated but not resulting in excessive movement	

CarCheck.co.uk page 3/13



MOT #10 2017-01-12 11:56

MOT test number 298785202515

Result ✓ Passed

▼ Tubsec

MOT #9 2015-12-30 11:37

MOT test number 946268590049

Result ✓ Passed

MOT #8 2015-12-30 11:37

MOT test number 158502189166

Result X Failed

Pass with rectification Offside Headlamp not working on dipped beam (1.7.5a)

MOT #7 2015-01-12 16:22

MOT test number 797922815079

Result ✓ Passed

Notice Items removed from driver's view prior to test

MOT #6 2015-01-10 10:00

MOT test number 385830115068

Result ★ Failed

Fail Offside Rear Direction indicator incorrect colour (1.4.A.2f)

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Items removed from driver's view prior to test

Fail Nearside Registration plate lamp not working (1.1.C.1d)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/13



2013-12-30 10:11 **MOT #5** 137774163348 **MOT** test number Result ✓ Passed **MOT #4** 2013-01-04 08:56 **MOT test number** 846354903026 Result ✓ Passed Offside Front Tyre worn close to the legal limit (4.1.E.1) **Advice Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT test number

Result

Fail Offside Windscreen washer provides insufficient washer liquid (8.2.3)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2

MOT test number

907666202031

Result

Notice Items removed from driver's view prior to test

CarCheck.co.uk page 5/13



MOT #1 2011-01-10 16:18
MOT test number 999170211047

MOT test number

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/13





Tax & MOT check



X MOT

Tax expired: 31 January 2022

Expired: 11 January 2022

Tax status	Expired at 31 January 2022
Days left	820 days too late
MOT expiry date	11 January 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	UK SIP
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-11-27
Last registration	2021-01-11
Complete history	See info



Registration #1	2007-11-27	21 mi
Registration #2	2011-01-10	52.068 mi
Registration #3	2012-01-06	68.875 mi
Registration #4	2013-01-03	85.295 mi
Registration #5	2013-01-04	85.298 mi
Registration #6	2013-12-30	106.318 mi
Registration #7	2015-01-10	126.654 mi
Registration #8	2015-01-12	126.654 mi
Registration #9		11.777 es
Registration #9 Registration #10		11.777 es
		11.777 es 11.777 es 11.777 es
Registration #10		11,777 es
Registration #10 Registration #11		11,777 es 11,777 es 11,777 es 11,777 es
Registration #10 Registration #11 Registration #12		11,777 est 11,777 est 11,777 est 11,777 est 11,777 est
Registration #10 Registration #11 Registration #12 Registration #13		11,777 est 11,777 est 11,777 est 11,777 est 11,777 est 11,777 est

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2850 mm
Kerb weight	1491 kg
Max. allowed weight	2090 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13

Engine number

7J08915