





report date: 2024-03-28

General information

Make	KIA
Model	SORENTO CRDI KX-3
Colour	Silver
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	194 BHP
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
CO2 emission	177 g/km
CO2 label	I



CarCheck.co.uk page 1/12



report date: 2024-03-28


Internet history

Entry 1

Date 2021-02-01

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

M		history
	\cup	IIISLUIV

MOT expiry date	2024-10-23
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	19
Total items failed	1

MOT #12	2023-10-04 14:01
MOT test number	627355820701
Result	✓ Passed
Next expiry date	2024-10-23

MOT #11	2022-10-24 16:14
MOT test number	450812524634
Result	✓ Passed

MOT #10	2021-10-11 16:11
MOT test number	706347315642
Result	✓ Passed

MOT #9	2020-09-26 14:00
MOT test number	438621031642
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #8 2019-10-12 12:07 **MOT** test number 770218490813 Result ✓ Passed **Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **Advice** Brake pipe corroded, covered in grease or other material both front to rears (1.1.11 (c)) Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

2019-10-12 12:07 **MOT #7** 881682886944 **MOT test number** Result × Failed **Advice** Brake pipe corroded, covered in grease or other material both front to rears (1.1.11 (c)) Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii)) Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) **Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #6	2018-10-11 10:21
MOT test number	530425630082
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5 2018-10-04 10:12

MOT test number 623347813492

Result X Failed

MAJOR Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2017-10-31 10:25

MOT test number 713600797758

Result \rightarrow Passed

Advice Offside Rear Inner Brake pad(s) wearing thin (3.5.1g)

Advice Front brake discs lipped on inner face

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2016-11-21 12:09

MOT test number 229336140309

Advice Nearside Rear fog lamp inoperative

MOT #2 2015-11-16 11:37

MOT test number 775324159917

Result ✓ Passed

MOT #1 2014-11-24 10:46

MOT test number 877498024395

Result

Passed

CarCheck.co.uk page 5/12



SB61EKM report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 May
Days left	367
MOT expiry date	23 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>have</u>	

THE STATE OF THE S	

	More info >
<u></u>	
Plate changes	
Cooling their shoots if their IVIA had different mumber plates	
See in this check if this KIA had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK O
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-11-30
Last registration	2023-10-04
Complete history	See info



Registration #1	2011-11-30	20 mi
Registration #2	2014-11-24	19.941 mi
Registration #3	2015-11-16	27.786 mi
Registration #4	2016-11-21	36.177 mi
Registration #5	2017-10-31	45.333 mi
Registration #6	2018-10-04	61.962 mi
Registration #7	2018-10-11	62.099 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	87%
Children	84%
Pedestrian	44%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1885 mm
Height	1755 mm
Length	4685 mm
Wheel base	2700 mm
Kerb weight	1896 kg
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/1

Engine number

D4HBBH023291