



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 SPORT D V50
Colour	Blue
Year of manufacture	2009
Top speed	127 mph
0 - 60 mph	9.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	153 g/km
CO2 label	G





Internet history

Entry 2

Date	2023-03-20
Pictures	24
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2022-08-04
Pictures	22
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2025-04-19
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	18
Total items failed	10

MOT #18	2024-04-09 13:04
MOT test number	530198980612
Result	✓ Passed
Next expiry date	2025-04-19
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17	2024-04-09 13:04
MOT test number	370154671459
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2023-03-21 14:42
MOT test number	191375461964
Result	✓ Passed

**MOT #15**

2022-04-20 11:19

MOT test number

365743920441

Result

✓ Passed

Advice Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement slight play found in strut when on turning plates (5.3.4 (a) (i))

MOT #14

2022-04-07 10:30

MOT test number

435644065353

Result

✗ Failed

Fail Nearside Rear Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Offside Headlamp aim too high and too far to the right. (4.1.2 (a))

Advice Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement slight play found in strut when on turning plates (5.3.4 (a) (i))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

MOT #13

2021-03-12 15:51

MOT test number

808985067212

Result

✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2021-03-12 15:51**MOT test number** 822626287382**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2020-03-11 16:30**MOT test number** 816628097203**Result** ✓ Passed**MOT #10** 2019-03-18 17:23**MOT test number** 174928143393**Result** ✓ Passed**MOT #9** 2017-12-14 12:23**MOT test number** 793410274524**Result** ✓ Passed**MOT #8** 2017-01-11 16:18**MOT test number** 397958768181**Result** ✓ Passed**MOT #7** 2016-01-13 17:06**MOT test number** 957344990611**Result** ✓ Passed

**MOT #6** 2016-01-13 17:06**MOT test number** 517439750795**Result** ✗ Failed**Pass with rectification** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #5** 2015-01-06 09:35**MOT test number** 117566505035**Result** ✓ Passed**Notice** Offside front tyre tread slightly scrubbing on inner edge**MOT #4** 2014-01-07 12:48**MOT test number** 816677004009**Result** ✓ Passed**MOT #3** 2013-01-02 11:28**MOT test number** 447352003037**Result** ✓ Passed**Notice** Stone chips in windscreen**Notice** Front discs worn**Notice** Sills covered**Notice** Tow ball/hitch not fitted at time of test**MOT #2** 2012-01-04 16:05**MOT test number** 858074002077**Result** ✓ Passed



MOT #1	2012-01-04 16:05
MOT test number	495124202029
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too low (1.8)
Pass with rectification	Offside Headlamp aim too low (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
19 April 2025

Tax status	Valid until 1 October
Days left	155
MOT expiry date	19 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-01-12
Last registration	2024-04-09
Complete history	See info



Registration #1	2009-01-12	16 mi
Registration #2	2012-01-04	27.265 mi
Registration #3	2013-01-02	33.214 mi
Registration #4	2014-01-07	40.090 mi
Registration #5	2015-01-06	46.235 mi
Registration #6	2016-01-13	53.554 mi
Registration #7	2016-01-13	53.554 mi
Registration #8	2017-01-11	60.748 mi
Registration #9	2017-12-14	67.067 mi
Registration #10	2019-03-18	80.146 mi
Registration #11	2019-03-18	80.146 mi
Registration #12	2019-03-18	80.146 mi
Registration #13	2019-03-18	80.146 mi
Registration #14	2019-03-18	80.146 mi
Registration #15	2019-03-18	80.146 mi
Registration #16	2019-03-18	80.146 mi
Registration #17	2019-03-18	80.146 mi
Registration #18	2019-03-18	80.146 mi
Registration #19	2019-03-18	80.146 mi
Registration #20	2019-03-18	80.146 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1489 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	521737