



AJ59MZO

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF SE TDI
Colour	Black
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	250 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	57.7 mpg



LABEL UNKNOWN



MOT history

MOT #13	2020-12-22 10:38
MOT test number	916597515956
Result	✓ Passed
Next expiry date	2022-01-07
Advice	Front Inner Brake pad(s) wearing thin close to wear indicator (1.1.13 (a) (ii))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Advice	Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #12	2020-01-08 15:22
MOT test number	814571122009
Result	✓ Passed

MOT #11	2019-12-06 09:36
MOT test number	958304118197
Result	✓ Passed
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10	2019-12-05 16:52
MOT test number	191667674689
Result	✗ Failed
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
MAJOR	Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



MOT #9	2018-11-26 14:56
MOT test number	702576415346
Result	✓ Passed
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #8	2018-11-23 14:52
MOT test number	538968333464
Result	✗ Failed
MAJOR	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Nearside Side repeater not working (4.4.1 (a) (ii))
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
MAJOR	Offside Rear Service brake excessively binding (1.2.1 (f))
Advice	Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #7	2017-12-01 12:54
MOT test number	498673387872
Result	✓ Passed
Advice	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush wish bone starting to peel (2.4.G.2)
Advice	Nearside Direction indicator has light sources not illuminating, but not more than 50% mirror indicator only has 50% of light working (1.4.A.2c)
Advice	Offside Front Shock absorber has a light misting of oil (2.7.3)
Advice	Nearside Front Shock absorber has a light misting of oil (2.7.3)



MOT #6	2016-11-15 14:37
---------------	------------------

MOT test number	623952365216
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2015-11-20 13:59
---------------	------------------

MOT test number	592462358990
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2015-11-20 13:59
---------------	------------------

MOT test number	853729135935
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification

Windscreen wiper does not clear the windscreen effectively both front wiper blades (8.2.2)

MOT #3	2014-11-14 16:35
---------------	------------------

MOT test number	797618014304
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2013-11-28 14:52
---------------	------------------

MOT test number	865132333327
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2012-11-29 09:06
---------------	------------------

MOT test number	378904132380
------------------------	--------------

Result	✓ Passed
---------------	----------



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2019-01-01
Current registration	 XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-11-30
Last registration	2020-12-22
Complete history	See info



Registration #1	2009-11-30	6 mi
Registration #2	2012-11-29	30.077 mi
Registration #3	2013-11-28	39.930 mi
Registration #4	2014-11-14	50.853 mi
Registration #5	2015-11-20	61.154 mi
Registration #6	2015-11-20	61.154 mi
Registration #7	2016-11-15	71.949 mi
Registration #8	2017-11-15	82.744 mi
Registration #9	2018-11-15	93.539 mi
Registration #10	2019-11-15	104.334 mi
Registration #11	2020-11-15	115.129 mi
Registration #12	2021-11-15	125.924 mi
Registration #13	2022-11-15	136.719 mi
Registration #14	2023-11-15	147.514 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1266 kg
Max. allowed weight	1870 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	CBD 106784