





report date: 2024-03-29

#### General information

Make	FORD
Model	FUSION ZETEC CLIMATE
Colour	Blue
Year of manufacture	2008
Top speed	109 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed automatic

### Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 сс
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.2 mpg
CO2 emission	181 g/km
CO2 label	I



CarCheck.co.uk page 1/13



report date: 2024-03-29

# Internet history

#### Entry 1

Date 2021-01-30

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-07-14
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	10
Total items failed	5

MOT #16	2023-07-15 10:32
MOT test number	912570460486
Result	✓ Passed
Next expiry date	2024-07-14
Advice Offside Rear Tyre slightly damaged/cracking or perishing 2mm inner tread	(5.2.3 (d) (ii))
Advice Rear Coil spring corroded both (5.3.1 (b) (i))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Minor Nearside Front Position lamp has a product on the lens or light source which light intensity (4.2.3 (b) (i))	obviously reduces

MOT #15	2022-07-13 11:57
MOT test	<b>number</b> 459279579636
Result	✓ Passed
<b>Advice</b> (1.1.14 (a)	Front Brake disc worn, pitted or scored, but not seriously weakened very corroded inner condition (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 3/13



report date: 2024-03-29

**MOT #14** 2022-07-13 11:57

**MOT test number** 825225084664

**Result** X Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened very corroded inner condition (1.1.14 (a) (ii))

Pass with rectification

Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #13** 2021-06-04 12:49

**MOT test number** 748970836930

Result \( \sqrt{Passed} \)

**MOT #12** 2019-06-06 09:28

**MOT test number** 952407590548

Result \( \sqrt{Passed} \)

Advice Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

**MOT #11** 2019-06-06 09:28

**MOT test number** 167477464552

Result × Failed

**Pass with rectification** Fuel cap/sealing device missing (6.1.3 (b) (i))

**Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

Pass with rectification Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #10 2018-05-16 14:05

MOT test number 534287224331

**Result** ✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #9		2017-06-07 08:31
MOT test number		741022521187
Result		<b>✓</b> Passed
MOT #8		2016-05-31 11:53
MOT test number		136549386948
Result		✓ Passed
MOT #7		2016-05-31 11:53
MOT test number		760879364204
Result		× Failed
Pass with rectification	Rear Stop lamp not working offside and nearside (1.2.1b)	
MOT #6		2015-03-31 09:24
MOT test number		819520995046
Result		<b>✓</b> Passed
MOT #5		2014-03-10 15:58
MOT test number		185589964054
Result		✓ Passed
MOT #4		2013-04-03 09:29
MOT test number		106813693036
Result		✓ Passed
MOT #3		2012-03-20 16:34
MOT test number		765060982038
Result		✓ Passed

CarCheck.co.uk page 5/13



Result

PL57FPY report date: 2024-03-29

✓ Passed

MOT #2

MOT test number

629954691070

Result

✓ Passed

MOT #1

2011-01-19 10:50

MOT test number

709119911091

CarCheck.co.uk page 6/13



## Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	14 July 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	T
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

*		
For how long did the current and previous owner(s) have this FORD? How many owners defect it in the premium report and see all owner registrations. Download the full report is		ave?
********		
***************************************		
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		,
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-29

#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



# Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-01-25
Last registration	2023-07-15
Complete history	See info



Registration #1	2008-01-25	13 mi
Registration #2	2011-01-19	11.794 mi
Registration #3	2011-04-04	12.608 mi
Registration #4	2012-03-20	17.564 mi
Registration #5	2013-04-03	22.839 mi
Registration #6	2014-03-10	26.848 mi
Registration #7	2015-03-31	29.599 mi
Registration #8	2016-05-31	36.793 mi
Registration #9	2016-05-31	36.793 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 au

More info >

CarCheck.co.uk page 12/13



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1110 kg
Max. allowed weight	1630 kg

# Additional information

Fuel tank capacity	45 l	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pa	age 13/13

Number of axles2Engine number8L44829