



General information

Make	NISSAN
Model	PIXO N-TEC
Colour	Grey
Year of manufacture	2010
Top speed	93 mph
0 - 60 mph	17.0 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	54.3 mpg
CO2 emission	122 g/km
CO2 label	D






Internet history

Entry 1

Date	2021-12-31
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-01-18
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	13
Total items failed	18

MOT #15	2023-01-19 12:49
MOT test number	807837279210
Result	✓ Passed
Next expiry date	2024-01-18

MOT #14	2023-01-16 15:21
MOT test number	189280156819
Result	✗ Failed
Fail	Offside Front Headlamp insecure (4.1.1 (c))
Advice	Nearside Rear TYRE AT 3MM
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear TYRE AT 3MM

MOT #13	2021-10-15 13:44
MOT test number	463748360179
Result	✓ Passed
Advice	Front Headlamp has a product on the lens but not seriously reducing light output BOTH (4.1.4 (b))
Advice	Rear Bumper mountings corroded but not likely to become detached BOTH SIDE (6.1.4 (a) (i))

**MOT #12** 2020-10-15 12:40**MOT test number** 532066737821**Result** ✓ Passed**Advice** Rear Bumper mountings corroded but not likely to become detached Both side (6.1.4 (a) (i))**MOT #11** 2019-09-14 11:31**MOT test number** 209782392280**Result** ✓ Passed**MOT #10** 2018-09-06 16:28**MOT test number** 552729336006**Result** ✓ Passed**MOT #9** 2018-09-06 11:14**MOT test number** 114528316285**Result** ✗ Failed**Fail** Stop lamp(s) not working Both side (4.3.1 (a) (ii))**Fail** Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))**Advice** O/S front bumper slightly damage**Fail** Offside Headlamp insecure (4.1.1 (c))**Fail** Registration plate lamp does not illuminate simultaneously with the position lamps Both side (4.7.2 (a))**Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #8** 2018-08-01 12:23**MOT test number** 307159083615**Result** ✗ Failed

- Fail** Offside Front Headlamp insecure (4.1.1 (c))
- Fail** Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))
- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Offside Rear Bumper mountings corroded but not likely to become detached (6.1.4 (a) (i))
- Fail** Fuel cap/sealing device ineffective (6.1.3 (b) (i))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))
- Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Fail** Nearside Rear Stop lamp(s) all not working (4.3.1 (a) (iii))
- Advice** Offside Front Bumper mountings corroded but not likely to become detached (6.1.4 (a) (i))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #7** 2017-08-09 12:16**MOT test number** 971911769031**Result** ✓ Passed

**MOT #6** 2017-08-05 10:56**MOT test number** 366820873030**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Anti-lock braking system warning lamp is missing. (3.4.1a)**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Nail in tyre**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2016-08-26 10:10**MOT test number** 249366949260**Result** ✓ Passed**MOT #4** 2015-09-02 18:37**MOT test number** 186815845208**Result** ✓ Passed**MOT #3** 2015-09-02 12:34**MOT test number** 986705745236**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2015-04-23 15:06**MOT test number** 246343715432**Result** ✓ Passed



MOT #1	2014-03-17 17:46
MOT test number	527306074000
Result	✓ Passed



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-09-29
Current registration	 *****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-08-13
Last registration	2023-01-19
Complete history	<a href="#">See info</a>



Registration #1	2010-08-13	25 mi
Registration #2	2014-03-17	25.992 mi
Registration #3	2015-04-23	30.633 mi
Registration #4	2015-09-02	31.310 mi
Registration #5	2015-09-02	31.310 mi
Registration #6	2016-08-26	42.205 mi
Registration #7	2017-08-05	58.353 mi
Registration #8	2017-08-09	58.353 mi
Registration #9	2018-08-01	72.464 mi
Registration #10	2019-05-29	95.277 mi
Registration #11	2019-05-29	95.277 mi
Registration #12	2019-05-29	95.277 mi
Registration #13	2019-05-29	95.277 mi
Registration #14	2019-05-29	95.277 mi
Registration #15	2019-05-29	95.277 mi
Registration #16	2019-05-29	95.277 mi
Registration #17	2019-05-29	95.277 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	121456