





report date: 2024-03-28

# General information

Make	PEUGEOT
Model	107 ACCESS
Colour	Red
Year of manufacture	2012
Top speed	99 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/13



# Internet history

## Entry 2

Date 2022-02-03

Pictures 7

Listing price <u>View report</u>









source: autotrader.co.uk

#### Entry 1

Date	2021-02-03	
Pictures	1	
Listing price	View report	



source: autoonline.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-11-07
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	13
Total items failed	9

MOT #15	2023-11-07 17:06
MOT test number	248119590520
Result	✓ Passed
Next expiry date	2024-11-07

MOT #14	2022-11-08 11:45	
MOT test	<b>number</b> 533891027406	;
Result	✓ Passed	I
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		

MOT #13		2022-02-11 12:48
MOT test nu	ımber	326479448223
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened b	ooth (1.1.14 (a) (ii))

MOT #12	2021-07-01 07:58
MOT test number	906104392017
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-28

**MOT #11** 2021-07-01 07:58

**MOT test number** 207024337329

**Result** X Failed

Pass with rectification Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #10** 2020-06-01 10:48

MOT test number 949240669359

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #9 2019-05-31 10:20

MOT test number 488229422737

Result 

Passed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Change now (5.2.3 (e))

MOT #8 2019-05-31 09:51

MOT test number 204222322977

Result × Failed

Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge Change now (5.2.3 (e))

**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #7 2018-05-30 10:39

**MOT test number** 751363227493

Result 

Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/13



**MOT #6** 2018-05-30 09:17

**MOT test number** 683684509159

Result X Failed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Nearside Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #5 2017-06-27 12:32

**MOT test number** 849775687342

**Result** ✓ Passed

**MOT #4** 2017-06-27 08:46

MOT test number 100386294146

**Result** ★ Failed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)

**Fail** Emissions not tested (7.3.A.1)

Advice Nearside Rear Tyre worn close to the legal limit Very low on edge (4.1.E.1)

**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

MOT #3 2016-06-30 09:23

MOT test number 732449269884

CarCheck.co.uk page 5/13



MOT #2 2016-06-30 09:23

**MOT test number** 987322674473

Result × Failed

Pass with rectification Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #1** 2015-06-03 11:29

**MOT test number** 829174255162

CarCheck.co.uk page 6/13



# Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	7 November 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 7/13



report date: 2024-03-28

# Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



funder scincole

EN12XUB

report date: 2024-03-28

More info >

# Owner history For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this PEUGEOT had different number plates. ober of plates

CarCheck.co.uk page 10/13



report date: 2024-03-28

# Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >


CarCheck.co.uk page 11/13



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2012-06-29
Last registration	2023-11-07
Complete history	See info



Registration #1	2012-06-29	21 mi
Registration #2	2015-06-03	36.936 mi
Registration #3	2016-06-30	59.127 mi
Registration #4	2016-06-30	59.127 mi
Registration #5	2017-06-27	76.205 mi
Registration #6	2017-06-27	76.205 mi
Registration #7	2018-05-30	92.553 mi
Registration #8	2018-05-30	92.553 mi
Registration #9	2019-05-31	110.720 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		77.777 au

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

# Dimensions & weight

Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg

# Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	7155098

CarCheck.co.uk page 13/13