



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 R-DESIGN
Colour	Blue
Year of manufacture	2013
Top speed	130 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-01-22
Pictures	7
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-05-04
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	13
Total items failed	0

MOT #9	2023-05-04 14:26
MOT test number	791535122319
Result	✓ Passed
Next expiry date	2024-05-04

MOT #8	2022-04-29 13:14
MOT test number	744489709516
Result	✓ Passed

MOT #7	2022-04-28 14:14
MOT test number	325410951501
Result	✗ Failed
DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #6	2021-05-05 12:23
MOT test number	978080650463
Result	✓ Passed

**MOT #5** 2021-04-27 09:46**MOT test number** 554336577586**Result** ✗ Failed**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))**MAJOR** Nearside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**MAJOR** Exhaust hydrocarbon content after 2nd fast idle exceeds default limits (8.2.1.2 (b))**DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MAJOR** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Minor** Offside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**MOT #4** 2019-12-02 10:18**MOT test number** 427218343776**Result** ✓ Passed**MOT #3** 2018-06-16 11:45**MOT test number** 144435188451**Result** ✓ Passed**MOT #2** 2017-06-14 13:28**MOT test number** 270713555423**Result** ✓ Passed



MOT #1	2016-06-06 13:39
MOT test number	403656414605
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
4 May 2024

Tax status	Valid until 1 May
Days left	367
MOT expiry date	4 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-06-14
Last registration	2023-05-04
Complete history	See info



Registration #1	2013-06-14	27 mi
Registration #2	2016-06-06	20.032 mi
Registration #3	2017-06-14	27.246 mi
Registration #4	2018-06-16	40.007 mi
Registration #5	2019-12-02	60.058 mi
Registration #6	2020-05-20	75.277 mi
Registration #7	2020-05-20	75.277 mi
Registration #8	2020-05-20	75.277 mi
Registration #9	2020-05-20	75.277 mi
Registration #10	2020-05-20	75.277 mi
Registration #11	2020-05-20	75.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1329 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1120703