



report date: 2024-03-29

General information

Make	VOLVO
Model	V40 D4 BUSINESS EDITION
Colour	Blue
Year of manufacture	2015
Top speed	140 mph
0 - 60 mph	7.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	178 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	65.7 mpg
Consumption extra urban	78.5 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A







Internet history

Entry 1

Date	2021-02-05
Pictures	24
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-01-21
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	6
Total items failed	3

MOT #8	2023-12-30 12:02
MOT test number	430203998365
Result	✓ Passed
Next expiry date	2025-01-21

MOT #7	2023-01-03 16:10
MOT test number	932760686476
Result	✓ Passed
Advice	Rear Tyre worn close to legal limit/worn on edge both rear tyres 2.0mm (5.2.3 (e))

MOT #6	2022-01-17 14:52
MOT test number	461234693123
Result	✓ Passed

MOT #5	2022-01-10 15:34
MOT test number	760056773348
Result	✗ Failed
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #4** 2021-01-22 15:53**MOT test number** 139624261318**Result** ✓ Passed**MOT #3** 2019-07-19 13:54**MOT test number** 195477580846**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing outer wall (5.2.3 (d) (ii))**MOT #2** 2019-07-19 10:48**MOT test number** 636555208642**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing outer wall (5.2.3 (d) (ii))**MOT #1** 2018-09-19 14:47**MOT test number** 883551822345**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**Advice** Offside Rear Tyre slightly damaged/cracking or perishing within tread (5.2.3 (d) (ii))**Advice** Child Seat fitted not allowing full inspection of adult belt



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
21 January 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	21 January 2025
Full MOT history	See MOT history

Tax calculation


Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-09-22
Last registration	2023-12-30
Complete history	See info



Registration #1	2015-09-22	20 mi
Registration #2	2018-09-19	67.782 mi
Registration #3	2019-07-19	89.583 mi
Registration #4	2019-07-19	89.584 mi
Registration #5	2021-01-22	114.504 mi
Registration #6	2022-05-22	151.277 mi
Registration #7	2022-05-22	151.277 mi
Registration #8	2022-05-22	151.277 mi
Registration #9	2022-05-22	151.277 mi
Registration #10	2023-12-30	151.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4635 mm
Wheel base	2776 mm
Kerb weight	1606 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1159399