



OU07YKM


report date: 2024-03-28

General information

Make	JAGUAR
Model	X-TYPE V6 SPORT
Colour	Blue
Year of manufacture	2007
Top speed	140 mph
0 - 60 mph	8.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	194 BHP
Max. torque	244 Nm at 3.000 rpm
Engine capacity	2.496 cc
Cylinders	6
Fuel type	Petrol
Consumption city	20.8 mpg
Consumption extra urban	39.2 mpg
Consumption combined	29.4 mpg
CO2 emission	234 g/km
CO2 label	L






Internet history

Entry 2


Date	2021-06-12
Pictures	17
Listing price	View report



source: autotrader.co.uk

Entry 1

Date	2021-05-20
Pictures	17
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-04-22
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	22
Total items failed	3

MOT #15	2022-04-23 13:56
MOT test number	157356347584
Result	✓ Passed
Next expiry date	2023-04-22
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #14**

2022-04-23 13:14

MOT test number

713723828803

Result

✗ Failed

- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))

MOT #13

2021-03-10 16:57

MOT test number

370862015259

Result

✓ Passed

MOT #12

2020-02-25 10:45

MOT test number

991107138430

Result

✓ Passed

MOT #11

2019-02-26 11:07

MOT test number

826857524270

Result

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Nail in tyre

**MOT #10** 2018-02-12 13:43**MOT test number** 124863889447**Result** ✓ Passed**MOT #9** 2017-03-03 13:17**MOT test number** 941324298408**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**MOT #8** 2017-03-03 13:17**MOT test number** 625741502352**Result** ✗ Failed**Advice** Nearside Rear Nail in tyre**Pass with rectification** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #7** 2016-03-04 11:35**MOT test number** 863342411749**Result** ✓ Passed**MOT #6** 2015-03-06 15:21**MOT test number** 537845265014**Result** ✓ Passed**MOT #5** 2014-03-07 14:06**MOT test number** 399206664043**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Nearside Front Road wheel slightly damaged (4.2.A.1a)

**MOT #4** 2013-03-04 16:25**MOT test number** 138873563084**Result** ✓ Passed**MOT #3** 2012-03-02 16:31**MOT test number** 617062762014**Result** ✓ Passed**MOT #2** 2011-03-07 09:33**MOT test number** 438516461048**Result** ✓ Passed**Notice** Front # plate cracked - secure and legible**Notice** Nail in offside rear tyre**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2010-03-19 15:04**MOT test number** 432858370013**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✕
Untaxed

Tax expired:
23 September 2022

✕
MOT

Expired:
22 April 2023

Tax status	Expired at 23 September
Days left	583 days too late
MOT expiry date	22 April 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	OU07YKM
Plate since	2019-09-28
Current registration	OU07YKM
Plate since	2019-09-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-03-30
Last registration	2022-04-23
Complete history	See info



Registration #1	2007-03-30	9 mi
Registration #2	2010-03-19	19.993 mi
Registration #3	2011-03-07	24.578 mi
Registration #4	2012-03-02	29.189 mi
Registration #5	2013-03-04	35.599 mi
Registration #6	2014-03-07	39.076 mi
Registration #7	2015-03-06	43.877 mi
Registration #8	2016-03-04	46.434 mi
Registration #9	2017-03-03	48.435 mi
Registration #10	2018-03-03	50.377 mi
Registration #11	2019-03-03	52.377 mi
Registration #12	2020-03-03	54.377 mi
Registration #13	2021-03-03	56.377 mi
Registration #14	2022-03-03	58.377 mi
Registration #15	2023-03-03	60.377 mi
Registration #16	2024-03-03	62.377 mi
Registration #17	2025-03-03	64.377 mi
Registration #18	2026-03-03	66.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1555 kg
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	554920419XB