





report date: 2024-03-28

General information

Make	RENAULT
Model	SCENIC I-MUSIC DCI
Colour	Silver
Year of manufacture	2010
Top speed	111 mph
0 - 100 km/h	12.4 seconds
0 - 60 mph	11.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	78 kW / 106 HP / 105 BHP
Max. torque	240 Nm at 2.000 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E



CarCheck.co.uk page 1/14



report date: 2024-03-28


Internet history

Entry 1

Date 2022-01-21


Pictures 25

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



RO60UUR report date: 2024-03-28

MOT history

MOT expiry date	2025-04-17
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	36
Total items failed	9

MOT #15	2024-04-05 08:19
MOT test number	745813547161
Result	✓ Passed
Next expiry date	2025-04-17
Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps (4.7.1 (b) (i))	or light sources
Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #14	2023-04-18 16:18
MOT test number	243724564481
Result	✓ Passed

Result		✓ rasseu
MOT #13		2022-01-04 16:26
MOT test	number	323687998966
Result		✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakene	ed corroded (1.1.14 (a) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened	ed corroded (1.1.14 (a) (ii))

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT #12 2021-02-12 14:00

MOT test number 913207537775

Result ✓ Passed

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Registration plate deteriorated but not likely to be misread Delaminating (0.1 (b))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Service brake requirements only just met. It would appear that the braking system requires adjustment or repair Possible seized calipers, pads barely in contact with disk on nearside. Small contact area. (1.2.1 (c))

MOT #11 2020-02-19 15:32

MOT test number 234961311095

Result \(\sqrt{Passed} \)

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #10 2020-02-19 12:15

MOT test number 397833646874

Result × Failed

Advice Offside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Front Registration plate inscription illegible excessively damaged (0.1 (b))

Fail Offside Rear Direction indicator incorrect colour (4.4.3 (a))

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

CarCheck.co.uk page 4/14



Advice

RO60UUR

report date: 2024-03-28

MOT test number

172440901684

Result

Advice Offside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #8 2019-02-22 11:12 **MOT** test number 412448949737 Result × Failed **Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Offside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c)) Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail Fail Nearside Rear Inner Brake disc significantly and obviously worn (1.1.14 (a) (i)) Fail Parking brake efficiency below requirements (1.4.2 (a) (i)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #7

MOT test number

Result

A Passed

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #6 2017-02-23 16:09

MOT test number 866805688274

MOT #5 2017-02-23 16:09

MOT test number 811558635600

Result X Failed

Pass with rectification Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

MOT #4 2016-02-15 10:23

MOT test number 510961266183

Advice Both front tyres worn on edges

Advice Engine covers and undertrays fitted

Advice Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Both front tyres low 3mm

Advice Childseat fitted

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT #3		2015-02-21 10:41
MOT test	number	826642555025
Result		✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Notice	Items removed from driver's view prior to test	
Notice	Oil leak	
Notice	Emissions too low to read	
Notice	Child seat fitted not allowing full inspection of adult belt	
Notice	Vehicle's internal headlight adjuster altered to recheck lights	
Notice	Under-trays fitted obscuring some underside components	

MOT #2	2014-02-25 16:18
MOT test number	698306154026
Result	✓ Passed
MOT #1	2013-11-13 11:40
MOT test number	557687413350
Result	✓ Passed
Notice Under-trays fitted obscuring some underside components	
Notice Nail in offside rear tyre	

CarCheck.co.uk page 7/14



RO60UUR report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	17 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

\sim	vner	L :	-4-	
- DV	vnar	nı	crc	T ()

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		AULT
manage of the same		

	More info	>
Plate changes		
See in this check if this RENAULT had different number plates.		
Number of plates		9
Current registration	NK SILE	
Plate since		
Current registration	UK NEZ	
Plate since		
	More info	>

CarCheck.co.uk page 11/14



report date: 2024-03-28

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-11-17
Last registration	2024-04-05
Complete history	See info



Registration #1	2010-11-17	9 mi
Registration #2	2013-11-13	28.414 mi
Registration #3	2014-02-25	28.939 mi
Registration #4	2015-02-21	41.926 mi
Registration #5	2016-02-15	54.628 mi
Registration #6	2017-02-23	67.332 mi
Registration #7	2017-02-23	67.332 mi
Registration #8	2018-02-22	75.971 mi
Registration #9	2019-02-22	86.551 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		0.00 44
Registration #17		D.777 es

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1486 mm
Height	1637 mm
Length	4344 mm
Wheel base	2703 mm
Kerb weight	1385 kg
Max. allowed weight	1935 kg

Additional information

Fuel tank capacity	49	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page	14/14

Number of axles2Engine numberD216709