




report date: 2024-03-28

General information

Make	NISSAN
Model	PATHFINDER DCI AVENTURA
Colour	Grey
Year of manufacture	2007
Top speed	112 mph
0 - 60 mph	11.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	169 BHP
Max. torque	403 Nm at 2.000 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel
Consumption city	23.5 mpg
Consumption extra urban	33.2 mpg
Consumption combined	28.8 mpg
CO2 emission	264 g/km
CO2 label	M





Internet history

Entry 3

Date	2022-02-27
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk

Entry 2

Date	2021-10-24
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk

Entry 1

Date	2021-10-23
Pictures	1
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2023-09-07
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	17
Total items failed	12

MOT #19	2022-09-03 09:46
MOT test number	217311902956
Result	✓ Passed
Next expiry date	2023-09-07

MOT #18	2022-08-30 11:56
MOT test number	499419337490
Result	✗ Failed
Fail	Nearside Rear Inner Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))

MOT #17	2021-09-04 08:09
MOT test number	615068077914
Result	✓ Passed
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Underside corroded

**MOT #16** 2020-09-08 09:52**MOT test number** 903582263718**Result** ✓ Passed**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #15** 2019-11-07 15:39**MOT test number** 259747577058**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2019-11-06 13:45**MOT test number** 260212837405**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm 255 65 17 (5.2.3 (e))**MOT #13** 2018-11-07 16:31**MOT test number** 747496704064**Result** ✓ Passed

**MOT #12** 2018-11-05 13:30**MOT test number** 738417488998**Result** ✗ Failed

- Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))
- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Nearside Rear Wheel bearing has excessive play (5.1.3 (a) (i))

**MOT #11** 2017-11-07 17:22**MOT test number** 718263588585**Result** ✓ Passed

- Advice** Nearside Front brake slightly binding

**MOT #10** 2016-10-24 15:21**MOT test number** 354728603293**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2016-10-21 08:16**MOT test number** 262395079616**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2015-11-09 12:28**MOT test number** 637766730618**Result** ✓ Passed**Advice** Centre Exhaust has a minor leak of exhaust gases silencer (7.1.2)**MOT #7** 2015-05-12 10:39**MOT test number** 517672235176**Result** ✓ Passed**MOT #6** 2014-05-30 15:16**MOT test number** 716630054134**Result** ✓ Passed**MOT #5** 2014-05-28 12:11**MOT test number** 365628844154**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)**Fail** Nearside Rear coil spring broken (2.4.C.1a)



MOT #4	2013-05-29 08:57
MOT test number	207429743150
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Notice	Engine covers fitted obscuring some components in the engine bay

MOT #3	2012-05-25 14:57
MOT test number	257776142469
Result	✓ Passed

MOT #2	2011-06-01 14:42
MOT test number	119102951104
Result	✓ Passed

MOT #1	2010-05-14 10:04
MOT test number	331234930194
Result	✓ Passed



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-06-01
Last registration	2022-09-03
Complete history	<a href="#">See info</a>



Registration #1	2007-06-01	22 mi
Registration #2	2010-05-14	27.618 mi
Registration #3	2011-06-01	36.115 mi
Registration #4	2012-05-25	43.685 mi
Registration #5	2013-05-29	51.008 mi
Registration #6	2014-05-28	56.831 mi
Registration #7	2014-05-30	56.882 mi
Registration #8	2015-05-12	656.061 mi
Registration #9	2015-11-09	65.531 mi
Registration #10	2016-10-21	72.230 mi
Registration #11	2016-10-24	72.230 mi
Registration #12	2017-11-07	81.712 mi
Registration #13	2018-05-29	91.277 mi
Registration #14	2018-05-29	91.277 mi
Registration #15	2018-05-29	91.277 mi
Registration #16	2018-05-29	91.277 mi
Registration #17	2018-05-29	91.277 mi
Registration #18	2018-05-29	91.277 mi
Registration #19	2018-05-29	91.277 mi
Registration #20	2018-05-29	91.277 mi
Registration #21	2018-05-29	91.277 mi
Registration #22	2018-05-29	91.277 mi
Registration #23	2018-05-29	91.277 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1850 mm
Height	1763 mm
Length	4740 mm
Wheel base	2850 mm
Kerb weight	2208 kg
Max. allowed weight	2880 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	865510