



PEUGEOT

**BL08HNA**

report date: 2024-03-29

General information

Make	PEUGEOT
Model	207 SPORT
Colour	Red
Year of manufacture	2008
Top speed	115 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	136 Nm at 4.000 rpm
Engine capacity	1.397 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.9 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg
CO2 emission	145 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-06-15
Pictures	8
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-06-08
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	34
Total items failed	3

## MOT #15 2023-06-07 13:28

MOT test number 685181022843

Result ✓ Passed

Next expiry date 2024-06-08

**Advice** Registration plate deteriorated but not likely to be misread front & rear (0.1 (b))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Coolant leak**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))

## MOT #14 2022-06-09 11:30

MOT test number 883003070535

Result ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #13** 2021-07-30 11:50**MOT test number** 634183369276**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge outer edges (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge outer edges (5.2.3 (e))**MOT #12** 2021-07-29 08:07**MOT test number** 883532147096**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge outer edges (5.2.3 (e))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge outer edges (5.2.3 (e))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #11** 2020-08-01 10:48**MOT test number** 536018364901**Result** ✓ Passed**Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Front Exhaust has a minor leak of exhaust gases joint area (6.1.2 (a))**MOT #10** 2019-04-20 13:00**MOT test number** 479603705386**Result** ✓ Passed**Advice** Front and centre exhaust mountings corroded /broken**Advice** Under trays and engine covers fitted

**MOT #9** 2019-04-20 09:50**MOT test number** 268360179262**Result** ✗ Failed**Advice** Front and centre exhaust mountings corroded /broken**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Under trays and engine covers fitted**MOT #8** 2018-04-28 11:18**MOT test number** 399004967906**Result** ✓ Passed**Advice** Front Inner Tyre worn close to the legal limit edges (4.1.E.1)**Advice** Exhaust mount crodded**MOT #7** 2017-04-22 12:09**MOT test number** 290971260756**Result** ✓ Passed**Advice** Nearside Rear tyre cracking**Advice** Under trays and engine covers fitted**Advice** Rear exhaust mounting corroded/broken**MOT #6** 2016-04-30 11:08**MOT test number** 306318757473**Result** ✓ Passed**Advice** Exhaust corrosion**Advice** Front Inner Tyre worn close to the legal limit 1856515 (4.1.E.1)

**MOT #5** 2015-05-06 09:53**MOT test number** 866146425130**Result** ✓ Passed**Notice** Ac pump oil seeping**Notice** Front exheust flexi correded**MOT #4** 2014-04-24 10:03**MOT test number** 415374714163**Result** ✓ Passed**Notice** Off side rear btyre cracking**MOT #3** 2013-04-25 09:20**MOT test number** 835555313138**Result** ✓ Passed**MOT #2** 2012-04-25 09:51**MOT test number** 359846412125**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #1** 2011-05-11 12:27**MOT test number** 457791331118**Result** ✓ Passed**Notice** Both front wipers smearing screen slightly.



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
8 June 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	8 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-09-29
Current registration	 *****
Plate since	2019-09-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-06-27
Last registration	2023-06-07
Complete history	<a href="#">See info</a>



Registration #1	2008-06-27	26 mi
Registration #2	2011-05-11	16.733 mi
Registration #3	2012-04-25	20.835 mi
Registration #4	2013-04-25	25.189 mi
Registration #5	2014-04-24	29.647 mi
Registration #6	2015-05-06	34.805 mi
Registration #7	2016-04-30	40.639 mi
Registration #8	2017-04-22	46.446 mi
Registration #9	2018-04-28	52.495 mi
Registration #10	2019-05-20	58.557 mi
Registration #11	2020-05-20	64.619 mi
Registration #12	2021-05-20	70.681 mi
Registration #13	2022-05-20	76.743 mi
Registration #14	2023-05-20	82.805 mi
Registration #15	2024-05-20	88.867 mi
Registration #16	2025-05-20	94.929 mi
Registration #17	2026-05-20	100.991 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1473 mm
Length	4037 mm
Wheel base	2540 mm
Kerb weight	1253 kg
Max. allowed weight	1640 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	FGAH0232170