



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	EOS TDI SE
Colour	Grey
Year of manufacture	2008
Top speed	127 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	156 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-02-28
Pictures	11
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-24
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	30
Total items failed	2

MOT #16	2024-03-25 11:05
---------	------------------

MOT test number	247059624605
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-03-24
------------------	------------

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15**

2024-03-20 12:37

MOT test number

312763078009

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Service brake efficiency below requirements (1.2.2 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Rear Brakes imbalanced across an axle (1.2.1 (b) (i))
- MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Front Brakes imbalanced across an axle (1.2.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Offside Front Service brake excessively binding (1.2.1 (f))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #14

2023-03-17 15:26

MOT test number

239708986653

Result**✓ Passed**

- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #13

2022-03-21 14:51

MOT test number

818099524264

Result**✓ Passed**

**MOT #12** 2021-06-22 15:06**MOT test number** 701684576501**Result** ✓ Passed**MOT #11** 2020-06-09 12:07**MOT test number** 443257362169**Result** ✓ Passed**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**MOT #10** 2019-06-22 09:23**MOT test number** 716130790923**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #9** 2018-06-23 10:37**MOT test number** 350907300247**Result** ✓ Passed**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #8** 2017-06-10 08:30**MOT test number** 483758504505**Result** ✓ Passed

**MOT #7** 2016-06-15 10:10**MOT test number** 310806612748**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2015-06-13 10:30**MOT test number** 635834465174**Result** ✓ Passed**Advice** Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**MOT #5** 2014-06-25 14:29**MOT test number** 339766874197**Result** ✓ Passed**MOT #4** 2013-06-21 14:55**MOT test number** 999532073193**Result** ✓ Passed**MOT #3** 2012-06-02 11:34**MOT test number** 477974852162**Result** ✓ Passed**MOT #2** 2011-06-16 11:28**MOT test number** 729667661196**Result** ✓ Passed



MOT #1	2011-06-16 11:28
MOT test number	809517561185
Result	✗ Failed
Pass with rectification	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
24 March 2025

Tax status	Valid until 1 April
Days left	338
MOT expiry date	24 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 VE08KYO
Plate since	2019-06-29
Current registration	 VE08KYO
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-06-27
Last registration	2024-03-25
Complete history	See info



Registration #1	2008-06-27	28 mi
Registration #2	2011-06-16	38.210 mi
Registration #3	2012-06-02	47.512 mi
Registration #4	2013-06-21	54.352 mi
Registration #5	2014-06-25	61.246 mi
Registration #6	2015-06-13	69.617 mi
Registration #7	2016-06-15	75.780 mi
Registration #8	2017-06-10	81.303 mi
Registration #9	2018-06-23	87.682 mi
Registration #10	2019-06-20	95.277 mi
Registration #11	2020-06-20	103.277 mi
Registration #12	2021-06-20	111.277 mi
Registration #13	2022-06-20	119.277 mi
Registration #14	2023-06-20	127.277 mi
Registration #15	2024-03-25	135.277 mi
Registration #16	2024-03-25	135.277 mi
Registration #17	2024-03-25	135.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1517 mm
Length	4774 mm
Wheel base	2709 mm
Kerb weight	1715 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BKP 293807